SURVEY & REMONUMENTATION

H.C.Miller

Stock No. 26273

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MAR 1 9 1997

COMMISSION

	Filing Requirement of Act 74, Mich. P.A. 1970				IRON COUNTY		
For corners in	: *				MIGHTAN RECEIVED FOR RECORD		
	cated in:	Corner Co	de #				
(County)	į į	3		1 0	95 DEC 23	an 9: Un	
	46N R 34W			, L.C	Regard	L. 1, P. 36	
	45N B 84W 4	N DYESTICOG	2)3,7		10 de 200	La Section	
<u>'</u> -	R R			e de la companya de La companya de la co	in and the second	n prens	
2. Property Controlling ST	R						
in Section ST_	R				•	\$	
3. Miscellaneous S T_ Property in Sec. S T_	N R			Regis	ter of Deeds St	amp & File Number	
			:				
4. Lot No, Recorded Plat 5. Private Claims		· · · · · · · · · · · · · · · · · · ·		1 [B	C D E F G	H I J K L I	
East Witness Corner				2 6		31	
Meander Corner between S.32, T46N				3	 		
S.5, T45N	⊦R34.W :	*	1	4 7		101112	
I, Gary L. Pisoni , in a field s	urvey on Octob	<u>er 18</u> , 19 <u>96</u>	do hereby state	5	 		
that under requirements of P.A. 74, Mich	nigan P.A. of 197	70, the corner poi	nts mentioned	618		151413	
in lines 1 and 2 above were in confor required in the current manual of survey				7	 		
the Interior, Bureau of Land Management	or by a decree of	a Court of Law a	nd /or that the	819-	20-2121	22	
corner points mentioned in lines 3, 4 and				9		 	
the Michigan Board of Land Surveyors of re-established, monumented, recovered, f			; established,	1030	-2928	27 26 25	
	!	li F		11			
NOTE: Not more than 2 corners, all in the sa	ame town and rang	ge, may be recorded		1231	3233	34 35 36	
on this certificate.	ř	* · · · · · · · · · · · · · · · · · · ·		13	<u> </u>		
	, '						
A. Description of original monument and	d accessories and	Vor subsequent re	storation:		•		
		§					
Original corner established by Willian	m Burt, U.S. Dep	uty Surveyor on S	eptember 18, 1	846.			
Original corner: 7" Spruce Corner tre	ee .			•			
Original bearing trees:	N 570 5	00 Selection (1	8.48 feet)				
Hemlock 14"	N 57° E	20 IIIKS (1	10.40 leeu				
B. Description of corner evidence found	d and/or method	applied in restorin	a or reestablishi	na corner:			
B. Description of comer evidence round	a dilator illication	uppliod iii routerii.					
in the second second	•			``.			
No original corner evidence found.							
Set Witness Corner Meander Corn	er on East shore	of Porter Lake, or	ine between th	ne North Q	uarter comer		
and Northeast Section corner of S	ection 5, 145N F	34W.	1		150. 200.		
:	1 :	: .			PEER GR	OUP APPROVED	
	1			. 1	Ron Sony J.	Prom 12-11-96 REPRESENTATIVE	
Corner Record Research on file wi	ith County Repres	sentative.	100		COUNTY	BEBBESENIAHA	
.C. Description of monument for corn		on antablished to r	ornetuate locati	ng the nos	ition of the co	mer	
			H				
At the corner position, I set a 5/8	diameter by 30)" rebar pin, 2" ab	ove ground surf	ace and			
and 12 feet from waters edge with Remonumentation, T46N, R34W,	th a 3" cast alum	iinum cap, stampe 2. S-5. T45N, 199	ed to read: Iron (96. RLS:27457 1	Jounty From which			
established the following new blan	zed and scribed i	bearing trees: (all	measurements t	aken to a r	nail in side of t	ree)	
Red Maple 7"	S 70°	' E ;	8.35 feet		CANTAL DI	MICHIO	
Cedar 6" White Pine 20"	S 20° N 67°		45.70 feet 6.22 feet		ALCANIE.	CANT	
Steel Sign Post 6'	N 52°		0.85 feet		* . y	RY L	
	: 1	:				ISONI A	
#96-14						RVEYOR	
Signed by Way L. Tom		Date <u>/2</u> -	10-96		* F	No. 5	
Surveyor's Michigan License No. 274	157	FOR	M APPROVED BY MICH	GAN STATE BOA	RD OF PROFESSIONAL	SURVEYORS VAN 28, 1971	
		1 - Dal			Trace CD	REMSED JAN., 1983	