

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Iron</u>	Located In:	Corner Code #
(County)		
1. Public Land Survey	T <u>45N</u> R <u>35W</u>	<u>L-13</u> ✓
	T <u>44N</u> R <u>35W</u>	<u>L-1</u>
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling	S _____ T _____ R _____	_____
in Section	S _____ T _____ R _____	_____
3. Miscellaneous	S _____ T _____ R _____	_____
Property in Sec.	S _____ T _____ R _____	_____

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:01

L. C. Reggelo: L. S. P. 242

Robert L. Pisoni
REGISTERED SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Quarter Corner to Section 36, T45N, R35W
Quarter Corner to Section 1, T44N, R35W

I, Gary L. Pisoni, in a field survey on April 3, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on September 16, 1846 by William A. Burt, U.S. Deputy Surveyor.

Original Corner; Fir Post

Original Bearing Trees:

Cedar	14"	N 30° E	19 links (12.54 feet)
Cedar	18"	N 10° W	19 links (12.54 feet)

On 10/18/72, Donald D. Lappala RLS USFS restored the quarter corner position from a found 4"x4"x60" wood post at record bearing and distance from the original bearing trees, set a 2" diameter by 5' long concrete filled iron pipe with a 3" diameter bronze tablet stamped as follows: T45N, R35W, 1/4, S-36, S-1, T44N, 1972, RLS 12585, recorded in

Liber 3, Page 138.

1972 Bearing Trees:

Sugar Maple	7"	N 06° E	38.8 feet
Sugar Maple	6"	S 12° W	22.1 feet
Yellow Birch	12"	S 82° W	17.0 feet
Steel sign post		N 28° E	2.1 feet

PEER GROUP APPROVED

Iron Gary L. Pisoni 11-30-2000
COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found remains of the cedar bearing tree stumps.

On 4/3/2000, found monument as described above and the following bearing trees:

Sugar Maple	12"	N 07° E	38.81 feet
Sugar Maple	8"	S 11° W	21.98 feet
Yellow Birch	14"	S 84° W	17.12 feet
Steel sign post		N 25° E	2.1 feet

Found existing bearing tree established by the U.S.F.S.

Red Maple	8"	S 75° E	25.34 feet
-----------	----	---------	------------

Monument is 18" above ground surface.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Established the following new reference object:

Steel Sign post	N 65° W	0.8 feet
-----------------	---------	----------

00-010

Signed by Gary L. Pisoni Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 28, 1975

LIBER 8 PAGE 242

