

LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: August 9, 2016

For corner(s) in: Iron County

Original Public Land Survey Corner

Corner Code

a. S T 46N R 32W D07 (GCDB 240400)
b. S T 46N R 32W G09 (GCDB 400300)
S T R
S T R

Property Corner

1/16 Corner Code

S T R
S T R
S T R
S T R

	A	B	C	D	E	F	G	H	I	J	K	L	M	
1														1
2	6			5		4		3		2		1		2
3														3
4	7			8		9		10		11		12		4
5														5
6	18			17		16		15		14		13		6
7														7
8	19			20		21		22		23		24		8
9														9
10	30			29		28		27		26		25		10
11														11
12	31			32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A. Corner History

a.) Quarter corner common to Sections 17 and 20. 1852 - Established by Francis Houck, U.S. Deputy. Set post midway and on the Section line between Section corners 40.00 ch. east and west. Fir 6" N42°E 30 links, Tam. 14" S48°W 28 links. Northern Paper Mills records: June 1931 - B.G. Buell and N.W. Ellison found 14" Tam. B.T. dead. Set post. March 1950 - D.L. Buell and N.J. Peryam found post. Rotten Tam. stump S48°W 28. March 1953 - S.R. Wickman and N.J. Peryam found post. Rotten Tam. Stump S48°W 28. Old lines and marks. Set pipe from rotten stump. Fits post exactly. Set iron pipe with brass cap. Cedar 9" N39°W 48 links, Cedar 12" N51°E 50 links.

b.) Corner common to Sections 21-22-27-28. 1852 - Established by Francis Houck, U.S. Deputy, presumed to have set a post. Sugar 12" N46°W 36 links, Fir 10" S64°E 22 links. Northern Paper Mills records: June 1931 - B.G. Buell and Ellison found post and Sugar B.T. NW I.M. plain. Dec. 1953 - S. Wickman and H. Gerry found post and rotten stump that fits notes. Set pipe beside post. Iron pipe with brass cap. Y. Birch 14" S42°E 55 links, Sugar 16" N22°W 70 links.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a.) Found the 1953 monument in good condition and at record bearing and distance from the 1953 witnesses. The Cedar NW is dead and down, the Cedar NE is in good condition with scribing visible. Accepted the monument as a careful and faithful perpetuation of the position of the original corner.

b.) Found the 1953 monument in good condition, inside of a 1-1/4" ID iron pipe, at record bearing and distance from the 1953 witnesses. The Y. Birch SE is a 5' high stub with scribing visible. The Sugar NW is a stump with lower face visible. Accepted the monument as a careful and faithful perpetuation of the position of the original corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

a.) Found 1" ID I. pipe with 2" brass Northern Paper Mills cap. Set measuring nail with MDNR tag in: 13" Cedar N53°E 33.8' old scribing (1953 NBT)
5" B. Spruce S32°E 5.25' mrkd "1/4S NBT"
5" B. Spruce S46°W 7.15' do
4" twin B. Spruce N37°W 11.5' do
E= 7897232.028 N= 177949.502

b.) Found 1" ID I. pipe with 2" brass Northern Paper Mills cap inside of 1-1/4" iron pipe. Set measuring nail with MDNR tag in the side of:
6" Sugar N83°E 12.15' mrkd "S22 NBT" w/poster
4" Sugar S35°E 13.9' "S27 NBT"
9" Sugar S70°W 5.35' "S28 NBT"
7" Sugar N62°W 16.65' "S21 NBT"
E= 7899601.738 N= 176310.881

Bearings are magnetic. Coordinates are MCS83, NAD83(2011) Epoch 2010.00, in meters
Coordinate Reference: MDNR Network control "BONE", a 1" ID I. pipe with 2" alum cap., E= 7899059.778 m. N= 176329.657 m.

Stephan J. Szyszkoski

10/13/2016



Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908