## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	6 T. / S., R. / E.	<u>₿-3</u>	
2. PROPERTY CONTROLL-	6 ,T. / S., R. / E.	B-3	
3. MISCELLANEOUS PROPERTY IN SECTION —			
	ECORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner points mentioned field survey on	d in lines 1 and 2 above (iden ————————————————————————————————————	ntified with circles on index d, re-established, monument ulations and rules therefore a the Interior, Bureau of Land tentioned in lines 3,4 and 5 established or re-established	P.A. 74, Michigan P.A. of 1970, code diagram – over) were, in a ed, re-monumented, recovered or as required in the current manual Management or by a decree of a above were, in a field survey on as expressed below and in controls or, by a Decree of a Court of
A. Description of original monument and accessories and/or subsequent restoration:			
	idence found and/or method ap		
	Angle Iron 1'abo		
from Consumer	ng Southerly, Easter 's Power Co., Jacks	MY, and westerly. Re	covered with Motes
, -	5 100007 105, 4400	<i>6,0,7,1,</i>	
C. Description of monumen	t for corner and accessories	established to perpetuate loc	eating the position of the corner:
•	l'above grouns		
<b>5</b> 65° W	476 Ruth	am i i de	
N 27° E	14.35' 7" N	le ole	
N89° E	14.35' 7" M	Marla	
	. , , ,	114/1/2	
SIGNED BY		DATE	
SURVEYOR'S MICHIGAN F	REGISTRATION NO.		(SEAL)
FOR STATE AND UNITED	STATES AGENCIES:		
SIGNED BY	CHIEF OF SURVEY PARTY	DATE	
		AND SURVEYOR DATE	(cru )
	MIGHIBAN REBISTEREU L	John L. Vii	(SEAL)