


STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

KALKASKA COUNTY
T 25 N R 7 W

DESCRIPTION OF CORNER E 1/4 corner Section 32
CORNER MONUMENT Added DNR Monument w/cedar guard post
DATE MONUMENT PLACED AND WITNESSED 1-11-72
WITNESSES TO CORNER..... 3" W. Pine N 87 W 126.5'



10" W. Pine N 50 W 114.0'
11" Maple 3-cluster N 33 W 77.0'
AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Recovered "Fargo" corner, 1912, 3/4" pipe, per M.S.H.D. survey.



SURVEYOR'S SEAL

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

SIGNED

Carl F. Roser

REGISTERED LAND SURVEYOR

DATE
12028

1-18-72