LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

	rung Kedane	SHELL OF ACT 74, IVIICI	
For Corners In: Kalkaska (County)	Located In	Corner Code #	
Public Land Survey	T _26N _ R_5W	Н8	
Property Controlling in Section	T R S 22 T 26N R 5W	1	
Miscellaneous Property in Section	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:		A B C D E F G H I J K L M
5. Private Claims:			2 6 5 4 3 2 1
I, <u>Craig W. McVean</u> , in a field survey on <u>September 29</u> , <u>2010</u> do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			
A. Description of original monument and accessories and/or subsequent restoration:			
<u>H8</u> – None	CRAIG W. MCVEAN PROFESSIONAL SURVEYOR No. 39088	Nav Drav	– Consumers Power Company Survey Map – ving No. S-F17406 – Duane A. Ankrom, PS 265 – ½" rebar set with C P CO Cap.
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: H8 – Center ¼, section 22, T26N, R5W - Set stamped 2" Aluminum Cap on 5/8" X 34" rebar at intersection of ¼ lines per Standard BLM Procedure. 1 – West 1/16 corner common to sections 15 and 22, T26N, R5W - Found ½" X 24" rebar. R5W - Found ½" X 24" rebar.			
C. Description of monun	nent for corner and accessories es	tablished to perpetuate	e locating the position of the corner
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: H8 - Set a stamped 2" Aluminum Cap on 5/8" x 34" rebar. 1 - Replaced found ½" X 24" Rebar with a stamped 2"			
Set Blue Carson S57°E 13.70' to S52°W 79.03' to N86°W 86.53' to	nite Post with location tag 1' Ea set nail & tag in SW. side 5" O set Nail & tag in NE. side 8" C set nail & tag N. side 5" R. Pir set nail & tag E. side 7" Oak	st Alumi Post v ak Dak S41°E ne S13°V S49°V	inum cap on 5/8" x 34" rebar With a stamped 2 inum cap on 5/8" x 34" rebar. Set Blue Carsonite with location tag 1' Southeast E 140.74' to set nail & tag in SW. side 4" W. Pine W 41.73' to set nail & tag in W. side 3" W. Pine W 51.45' to set nail & tag in NW side 3" W. Pine W 133.40' to set nail & tag in W. side 12" R. Pine
Signed by: Surveyor's Michigan	May MM () License No.: 39088	Date:	1/20/2011