



8 0 2 3 2 8 1

Tx:4016447

11/29/2012 1:00:00 PM

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Kalkaska

(County)

Located In

Corner Code #

1. Public Land Survey	T		R	
	T		R	
2. Property Controlling in Section	S 20	T 26N	R 6W	9
	S 20	T 26N	R 6W	13
3. Miscellaneous Property in Section	S	T	R	
	S	T	R	

4. Lot No: Recorded Plat:

5. Private Claims:

I, Joshua R. Davidson, in a field survey on Feb. 28, 2012 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Register of Deeds Stamp &amp; File Number

DOCUMENT #

3111423

JOANN DEGRAAF

KALKASKA CTY ROD

KALKASKA, MI

RECORDED ON

11/29/2012 1:31 PM

REC FEE: 14.00

PAGES: 1

BK: 3PG: 347

A. Description of original monument and accessories and/or subsequent restoration:

9 - 1901 - W. S. Merril, County Surveyor13 - none

1) Hemlock 26" N39°E 9½'

2) Cedar 6" S24°W 8½'

1975 - Certificate of Survey, L. 1, P. 651 & LCRC L. 1, P. 350

by N. F. Parker, PS #16939 - ½" x 18" iron bar.

3) Blaze on 8" Balsam N40°W 17.6'

4) Blaze on 7" Balsam S87°E 12.5'



B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

9 - CE 1/16 corner of Section 20. Found ½" x 18" rebar per Parker LCRC and witnesses #3 a stump and #4 fitting position. Steel fence post next to rebar. Found no county surveyor evidence. Replace found ½" X 18" rebar with a stamped 2" aluminum cap on a 5/8" X 34" rebar.

13 - SE 1/16 corner of section 20. Set stamped 2" aluminum Cap on 5/8" x 34" rebar per standard BLM procedure.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

9 - A stamped 2" aluminum cap on a 5/8" x 34" rebar. Replaced steel fence post 1' North.

13 - Set a stamped 2" Aluminum cap on 5/8" x 34" rebar

N05°E 43.56' to set nail & tag in W. side 3" Red Maple  
N83°E 12.32' to set nail & tag in N. side 10" Fir (#4)  
S27°E 38.98' to set nail & tag in E. side 4" Fir  
S84°W 26.01' to set nail & tag in S. side 5" Red Maple  
Set Blue Carsonite post with location tag 1' Southeast

N68°E 6.13' to set nail & tag in NW. side 2" Red Maple  
S28°E 7.70' to set nail & tag in E. side 3" Fir  
S70°W 20.75' to set nail & tag in NW. side 5" Elm  
N32°W 12.90' to set nail & tag in SW. side 3" Fir  
Set Blue Carsonite post with location tag 1' Northwest

Signed by:

Date:

11-29-2012

Surveyor's Michigan License No.:

46659