SURVEY & REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

FEB 26 2001

	Filing Require	ment of Act 74, Mich. P.A. 1	970
Far corners in			SECTION
KALKASKA	Located In:	Corner Code #	02011014
2000 REMONUMENTATION 1. Public Land Survey 2. Property Controlling S		M-6 /	
in Section S 3. Miscellaneous S Property in Sec. S	6 TR 6 TR 6 TR	**************************************	
4. Lot No, Records	ed Plat		
5. Private Claims			A B C D E F G H I J K L M
			2 5 5 4 3 2 1 3 4 7 8 9 9 10 11 12
I, <u>FUGENE FARRIER</u> , in a field survey on <u>August</u> , 20 00 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Burseu of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:		5	
NOTE: Not more than 2 corners, on this cartificate,	all in the same town and range,	may be recorded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration: M-6: 1/4 Cor. Common to Sec. 13. T27N-R7W. Kalkaska Two: A-6: Sec. 18.T27N-R6W. Excelsior Two. 1839: GLO survey by James H. Mullett; set 1/4 corner post at corner; Suger 18", S 77°W, 18 links; Suger 10", N 30°W, 12 links.			
1895: Survey by E.B. Dinnis, (Co. Surveyer) in BookPages 63 & 64; restored corner; from witness trees; (new) Beech 11", N 62°E, 21 links.			
1900: Survey by W.S. Merrill, (Co. Surveyor), in Old Liber 1 Page 27; stone corner, found original bearing trees of government survey.			
1974: LCRC by D.E. Porter in Liber 1 Page 315; set 1/2" rod cap at corner, by single proportion, fall in East shoulder of road; 9" Maple, N 75°W, 39.78'; 17" Bass, S 60°W, 41.55'; 13" Maple, S 38°W, 80.68'.			
1975 & 1977: Surveys by A.L. Dragoo in Liber 1 Page 770 and Liber 2 Page 199; found fron rod at corner.			
1975: LCRC by J.L. Wilcox in Liber 1 Page 383; found iron rod and cap #15410 at corner; 7" Maple, N 85°W. 39.84'; 14" Maple, S 70°W, 41.60'; 3" Elm, S 75°E, 15.48'.			
1989 & 1998; Surveys (not recorded) by N.B. DaYoung and by R. J. Kral, both found 1/2" rod at corner; 12" Meple, N 55°E, 47.30'; 3" Elm, N 49°E, 12.85'; 3" Elm, S 42°E, 21.30'; 1/2" rod, West 33.00'.			
1993: Survey (not recorded) by E. 13.05'; nail in 5" Elm, \$ 27°E, 21.			O' East of centerline road; nail in 5" Elm, N 45°E, g) West, 32.95'.
1998: Survey (not recorded) by R.J	J. Kral; found 1/2" Iron rod, sen	ne as 1989 & 1988 survey above.	
B. Description of corner evidence M-6: 1/4 Cor. Common to Sec. Found 1/2" Iron rod with partial caretanderd County monument.	13. T27N-R7W. Kalkaska T	wp: A-6: Sec. 18.T27N-R6W.	
No G.L.O. witnesses were found.		•	
N 23°E, 25.32', 3," Elm, set neil ar	. 13. T27N-R7W. Kalkaska T p at corner; 10" East of centerli nd tag	wp: A-6: Sec. 18.T27N-R6W. no N-S road (Resemburg Read): fo Raufied by Pee P.A. 345 - 1990	.Excelsior Two. und iron cep (N. DeYoung) West 32,95'. Added r Group) Kalkaska County
N 52°W, 13.03, 5° Elm, set nail er S 27°E, 21.60', 5" Elm, set nail er		Chairman	you farrie
S 27°E, 21.60', 5" Elm, set hall at West 32.95', iron and cap (N. DeY		Date	2-14-01
Kalkaska County Paer Group access	oted the above manument as a c		of the position of the original corner.
P	-2		
Signed by / Manhou	- Jano	Date	2-15-01
Signed by Canada Signed by Canada Michigan License No.	24594		
	TI LEN SIBIBIL BRES WEST I	emmania de de 30	26902 D OF PROPESSIONAL SURVEYORS, JAN. 28, 187