LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners in			
KALKASKA (County) 2000 REMONUMENTATION	Located In:	Corner Code #	SURVEY & REMONUMENTATION
1. Public Land Survey	T <u>27N</u> R <u>6W</u> TR T R		FEB 26 2001
2. Property Controlling S	TR TR TR TR	1 1111111111111111111111111111111111111	SECTION
4. Lot No, Recorded F	Plat		
5. Private Claims		·····	A B C D E F G H I J K L M 2 6 5 4 3 2 1 1 3 4 7 8 9 9 10 11 12
I, <u>EUGENE FARRIER</u> , state that under requirements of P.A. lines 1 and 2 above were in conform current manual of survey instructions of Management or by a decree of a Court and 5 above were in conformance with Decree of a Court of Law; established, below:	74, Michigan P.A. of 197 ence with regulations and f the United States Departr of Law and for that the or h the rules of the Michigan	70, the corner points mentioned in rules therefore as required in the ment of the Interior, Burseu of Land orner points mentioned in lines 3, 4 in Board of Land Surveyors or by a	6 18 17 16 15 14 13 7 7 9 19 20 21 22 23 24
NOTE: Not more than 2 comers, all in on this certificate.	the same town and range	e, may be recorded	11 12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration: C-6: 1/4 Cor. Common to Secs. 17. & 18. T27N-R6W. Excelsior Township 1852, G.L.O. Resurvey, by George H. Cennon, set Beech 8", post for corner; Beech 12", N87°E, 9 Lks 1886, Survey, by E. Mosher (Co. Surveyor), Co. Rd. Bk 9, Pg 5, tied into corner only 1971, LCRC, by N.F. Parker, Liber 1, Pg 53 & Survey in Liber 1, Pg 83, set 1/2" bar at corner by prorated distance and on line; 24" N. Pine, S62°E, 59.5°; 10° Birch,, 64.10' 1972, 1973, Surveys, by J.L. Wilcox, Liber 1, Pg 166 & Liber 1, Pg 283, found neil at corner; 10" Twin Birch, N70°E, 63.62'; 26" W. Pine, S57°E, 63.19'; conc. mon, N85°W, 41.56' 1973, Surveys, by C. Ostling, Liber 1, Pg 444, set 1/2" iron bar at corner; cluster 10" W. Birch, N78°W, 87.2'; 10" W. Birch, N62°E, 63.6'; 24" W. Pine, 571°E, 63.25' 1975-1988, Surveys, by J. Fletcher, Liber 1, Pg 672 (re-recorded) & Liber 2, Pg 193; & Survey by E. Farrier (Co. Surveyor), found 1/2" rerod at corner; 10° Birch, N70°E, 63.62'; 26" W. Pine, S57°E, 63.19'; conc. mon, N85°W, 41.56' 1988, Survey, by N. Livasy, found 1/2" rebar at corner; conc. mon, N85°W, 40.00'; 10" Twin Birch, N70°W, 63.62'; 26" W. Pine, S57°E, 63.19' 1989, Survey, by E. Farrier (Co. Surveyor), same as 1975 surveys above 1991-1993, Surveys, by E. Farrier (Co. Surveyor), same as 1975 survey above 1997-2000, Surveys, by E. Farrier (Co. Surveyor) same as 1975 survey above 1997-2000, Surveys, by E. Farrier (Co. Surveyor) same as 1975 survey above 1997-2000, Surveys, by E. Farrier (Co. Surveyor) same as 1975 survey above 1997-2000, Surveys, by E. Farrier (Co. Surveyor) same as 1975 survey above, centerline North-South road (Crawford Lake Road); found conc. mon. West 39.90'; nail in 6" Oak, N72°E, 41.41'; nail in 30" W. Pine, S55°E, 63.80'; nail in 6" W. Pine, S62°W, 84.77' 8. Description of corner evidence found and/or method applied in restoring or reestablishing corner: C-6: 1/4 Cor. Common to Secs. 17 & 18. T27N-R6W. Excelsior Townsh			
C. Description of monument for corn C-6: 1/4 Cor, Common to Secs. 17 Found 1/2" iron rod 2' West of centeril West, 39.90', found concrete monume N72°E, 414.41', 6" Oak, found nail S55°E, 63.80', 30" W. Pine, found nail S62°W, 84.77', 5" W. Pine, found nail Kaikaska County Paer Group accepted Ratified by Peer Group P.A. 345 - 1990 Kaika: Chairman Date	the above monument as co	elsior Township . Added brass remon cap & mon. b	00X
Signed by Surveyor's Michigan License No. 24	miss.	Date	2-15-01

3025824
Page: 1 of 1
02/18/2001 10:26A
REMON
LB: 6 PG: 153