		ER RECORDATION CERTIFIC	
For corners in	Filing Requi	irement of Act 74, Mich. P.A. 19	SURVEY &
KALKASKA	Located In:	Corner Code #	REMONUMENTATION
2000 REMONUMENTATION  1. Public Land Survey	T_27N R 6W TR	G-6	FEB 26 2001
2. Property Controlling in Section S 3. Miscellaneous S Property in Sec. S	T R T R _ T R _ T R _ T R		SECTION
4. Lot No, Recorded Pl	lat		
F 01 . 01 !	•		ABCDEFGHIJKL
5. Private Claims			. 1
			2 6 5 4 3 2 1 3
			4 7 8 9 10 11 12
I, EUGENE FARRIER , in a field	survey on August 21	. 20 00 do hereby state that under	5
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above			6 19 17 16 15 14 13
were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Lend Management or by a			7
decree of a Court of Law and /or that th	ne corner points mention	ed in lines 3, 4 and 5 above were in	8 19 20 21 22 23 24
conformance with the rules of the Mich Law; established, re-established, monum			9
NOTE: Not more than 2 comers, all in	4 4 <b>4</b>		10 30 29 28 27 26 25
NOTE: Not more than 2 comers, all in on this certificate.	CHO SENTIO TOWN BIRLING	ge, may be recomed	11
			12 31 32 33 34 35 36
S 50°E, 48.41'.  8-6-1974: LCRC by H.L. Fluharty in Liber 1979: Survey by J.L. Fletcher in Liber 2 59.85'; found nail 6" R. Pine, S 40°E, 4: 1983: Survey by N.B. DeYoung in Liber 2 Pine, N 60°E, 46.94'.  1996: Survey by R. J. Kral (not recorded 6" R. Pine, S 50°E, 48.41'.	8. 16. T27N-R6W. Exter post for corner; Sugaror) in Field Book 2 Page in Liber 1 Page 300-A; for 1 Page 353; found spil Page 353; found 1/2" b 8.48; found nail 7" R. I 2 Page 761; found 1/2" b; found cebin spike 1.5 #3026014; found spike	celsior Township or 12", S 64°W, 25 links; Yellow or 15; visited corner, no accessories ound cabin spike; 5" R. Pine, N 55°E ke; 6" Pine, N 57°E, 46.92'; 6" Pine, old spike 1.5' east centerline road on Pine, N 60°E, 46.94', boat spike; Nail in 8" Pine,S 55°W, is East of centerline road; 5" R. Pine, in 1" pipe on old fence line to West;	, 46.90'; 6" R. Pine, S 57°W, 59.90'; 6" R. Pine, S 51°E, 48.47'; 8" Pine, S 57°W, 59.92', fence line West; found nail, 8" R. Pine, S 55°W, 59.95'; Nail in 6" Pine, S 40°E, 48.48'; nail in 7" R N 55°E, 46.90'; 6" R. Pine, S 57°W, 59.90'; N 60°E, 12" R. Pine, 46.73'; 12" R. Pine, S 46°E,
B. Description of corner evidence found G-6: 1/4 Cor. Common to Secs. 15 a Found 1 1/2" pipe in centerline road N-S No G.L.O. witnesses were found.	& 16, T27N-R6W, Ex on fence line E-W; adde	celsior Township od 5/8* iron with brass cap.	
	Ratified by Peer Gr P.A. 345 - 1990 Ka	oup alkaska County	
	Chairman	mousie	OF MICHIGAN
	DateZ	-14-01	A GOVERNMENT OF THE PARTY OF TH
C. Description of monument for corner G-6: 1/4 Cor. Common to Secs. 15 & Found 1 1/2" pipe in centerline road N-S N 62°E, 46.30", 10" Red Pine, found na S 47°E, 48.53", 10" Red Pine, found na S 51°W, 69.95", 12" Red Pine, found na N 46°W, 64.25", 12" Red Pine	& 16. T27N-R6W. Ex on fence line E-W; edde ii il	celsior Township	on of the corner:   FARRIER PHOFESSIONAL SURVEYOR NO. 24594
Kalkaska County Peer Group accepted the above monument as the best aveilable evidence of the position of the original corner.			
Signed by	nie	Date	2-15-01



FORM APPROVED BY MICHGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 PEYISED MAY 14,1976 PEYISED JAN., 1982 PEYISED OCT., 1996