LAND CORNER RECORDATION CERTIFICATE			
For corners in	riing Requi	rement of Act 74, Mich. P.A. 1	SURVEY &
KALKASKA	Located In:	Corner Code #	REMONUMENTATION
(County) 2000 REMONUMENTATION 1, Public Land Survey	T_27N R_6W TR TR		FEB 2 6 2001 SECTION
2. Property Controlling S	TR TR TR TR		35011014
4. Lot No, Recorded Pla	ıt		
5. Private Claims			A B C D E F G H I J K L I
I, <u>EUGENE FARRIER</u> , in a field sur requirements of P.A. 74, Michigan P.A. o	f 1970, the corner point	ts mentioned in lines 1 and 2 above	· '
were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			6 19 17 16 15 14 13 7 8 19 20 21 22 23 24 9
NOTE: Not more than 2 corners, all in ti on this certificate.	ne same town and rang	e, may be recorded	10 30 29 28 27 26 25
OIL DIES COLORIGORO.			11 12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration: L5: Sec. Cor. Common to Secs. 10. 11. 14 & 15. T27N-R6W. Excelsior Township 1852: GLO resurvey by G.H. Cannon; set post for corner; B. Ash 10", N 85°W, 18 links; Ceder 12", 40°E, 17 links. 1876: Survey by D.E. McVean, visited corner, no accessories. 1902: Survey by E.D. Farrier in Liber 4 Page 16; found remains of two ceder stakes for corner in centerline roads; added 1/2" iron and cep; rivet in top of N end 24" CMP, N 70°E, 41.95"; 5" Maple, S 50°W, 62.49"; 9" Maple, N 70°W, 65.86"; 4" Ash, N 15°W, 25.14' 1992: Survey by E. Farrier (Co. Surveyor) (not recorded); found 1/2" iron and cep for corner, accessories same as survey recorded in Liber 4 Page 16. 1996: Survey by E. Farrier (Co. Surveyor) (not recorded); found 1/2" iron and cep for corner, accessories same as survey recorded in Liber 4 Page 16. 4-3-1999: Survey by R. Farrier (Co. Surveyor) (not recorded); found 1/2" iron and cep for corner, accessories same as survey recorded in Liber 4 Page 16. 4-3-1999: Survey by R. Farrier (Co. Surveyor) (not recorded); found 1/2" iron and cep for corner, accessories same as survey recorded in Liber 4 Page 16. 10-27-1999: Survey by E. Farrier (Co. Surveyor) (not recorded); found 1/2" iron and cep for corner, accessories same as survey recorded in Liber 4 Page 16. 10-27-1999: Survey by E. Farrier (Co. Surveyor) (not recorded); found 1/2" iron and cep for corner, accessories same as survey recorded in Liber 4 Page 16.			
B. Description of corner evidence found a 15: Sec. Cor. Common to Secs. 10. 1 Found 1/2* iron and cap #24594 1.5' Sou No G.L.O. witnesses were found.	1. 14 & 15. T27N-R	6W. Excelsior Township	outh. Added standard County monument.
C. Description of monument for corner at 1.5: Sec. Cor. Common to Sacs. 10. 1 Found 1/2" iron and cap #24594 1.5' Sou N 10°W, 24.98', 4" Elm, set nail & teg N 71°E, 76.70', 6" Elder, set nail & teg S 20°E, 79.30', 12" Ceder, set nail & teg S 66°W, 84.05', 6" Maple, set nail & tag	1. 14 & 15, T27N-R	6W. Excelsior Township	
Kalkaska County Peer Group accepted the	above monument as th	e best svailable evidence of the pos	ition of the original corner.
Ratified by Peer Group P.A. 345 - 1990 Kalkaska Coun Chairman Date			EUGENE D. FARRIER PROFESSIONAL SURVEYOR No. 24594

Signed by C. Surveyor's Michigan License No. 24594 3026845
Page: 1 of 1
e2/18/2001 10:28A
Ralkaska County Joan Hall, Ragister
LB: 6 PG: 174

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REFREE MAY 14, 1975
REVISED MAY 14, 1975
PEVISED DCT., 1995