



8 0 2 5 7 9 9

Tx:4018283

4/1/2013 2:15:00 PM

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:  
Kalkaska  
(County)

Located In

Corner Code #

1. Public Land Survey	T		R		
	T		R		
2. Property Controlling in Section	S 35	T 28N	R 7W		1
	S 35	T 28N	R 7W		2
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Joshua R. Davidson, in a field survey on October 2, 2012 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

DOCUMENT #

3113017

JOANN DEGRAAF

KALKASKA CTY ROD

KALKASKA, MI

RECORDED ON

04/01/2013 2:57 PM

REC FEE: 14.00

PAGES: 1

BK: 3PG: 356

Register of Deeds Stamp &amp; File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5			4			3		2	
3													
4	7			8			9			10		11	
5													
6	18			17			16			15		14	
7													
8	19			20			21			22		23	
9													
10	30			29			28			27		26	
11													
12	31			32			33			34		35	
13													

A. Description of original monument and accessories and/or subsequent restoration:

1 – W 1/16 corner common to sections 26 & 351902 - CSR – W.S. Merrill, survey and field notes, Bk. 45,  
P. 12, Pine Stump 40 S28W 481993 – Grand Traverse Surveying Company, Certificate of  
survey – file No. 93-2030 – iron set.2 – E 1/16 corner common to Sections 26 & 351902 - CSR – W.S. Merrill, survey and field notes, Bk. 45,  
P. 12,  
Pine Stump 50 N75W 35½  
Pine Stump 40 N37E 102

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

1 – W 1/16 corner common to sections 26 & 35.Found ½" X 18" rebar & cap #31611 per Grand Traverse  
Surveying Company, Certificate of survey file No. 93-2030.  
No county surveyor evidence was found. Accepted found  
rebar and cap as the best available evidence of the position  
of the corner and replaced it with a stamped 2" aluminum  
cap on 5/8" x 34" rebar.2 – E 1/16 corner common to Sections 26 & 35No county surveyor evidence was found. Set stamped 2"  
aluminum cap on 5/8" X 34" rebar per BLM standard  
procedure.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1 – a stamped 2" Aluminum Cap on 5/8" x 34" rebarNorth 33.10' to found ½" rebar  
S65°E 91.23' to set nail & tag in SW. side 12" W. Pine  
S17°E 42.01' to set nail & tag in E. side Twin 10" Cherry  
N69°W 56.75' to set nail & tag in NE. side 4" W. Pine  
Set blue Carsonite post with location tag 1' West2 – a stamped 2" Aluminum Cap on 5/8" X 34" rebar.N29°E 52.08' to set nail & tag in W. side 6" Cherry  
N82°E 79.53' to set nail & tag in S. side 12" Cherry  
S28°E 31.68' fd. 2½" O.D. iron pipe  
S07°W 44.05' to set nail & tag in E. side 12" R. Pine  
S80°W 34.48' to set nail & tag in N. side 15" Cherry  
Set blue Carsonite post with location tag 1' North

Signed by:

Surveyor's Michigan License No.: 46659

Date:

4-1-2013

