

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. PA 1970

For Corners In:  
Kalkaska  
(County)

Located In

Corner Code #

1. Public Land Survey	T		R	
	T		R	
2. Property Controlling in Section	S 35	T 28N	R 7W	3
	S 35	T 28N	R 7W	4
3. Miscellaneous Property in Section	S	T	R	
	S	T	R	

4. Lot No: Recorded Plat:

5. Private Claims:

I, Joshua R. Davidson, in a field survey on October 2, 2012 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

3 - N 1/16 corner common to sections 34 & 35

1920 - CSR - W.S. Merrill, survey and field notes, Bk. 45, P. 12, Cherry Stake, Iron buried, 1) Pine Stp 40 N45E 73

4 - NW 1/16 corner Section 35

1920 - CSR - W.S. Merrill, survey and field notes, Bk. 45, P. 12, no corner description given.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

3 - N 1/16 corner common to sections 34 & 35.

Found two 5" X 7" X 1/4" iron plates facing each other believed to be iron placed around stake. Found stump hole and remains of pine roots fitting position. Set a stamped 2" aluminum cap on 5/8" x 34" rebar between found iron plates.

4 - NW 1/16 corner Sections 35

No county surveyor evidence was found. Set stamped 2" aluminum cap on 5/8" X 34" rebar per BLM standard procedure.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3 - a stamped 2" Aluminum Cap on 5/8" x 34" rebar between iron plates

N35°E 77.57' to set nail & tag in NW. side 6" Cherry in clump  
S46°E 21.95' to set nail & tag in NE. side 9" Cherry  
S40°W 36.09' to set nail & tag in NE. side 5" R. Maple  
N61°W 85.78' to set nail & tag in NE. side 9" R. Maple in clump of 4  
Set blue Carsonite post with location tag 1' North

4 - a stamped 2" Aluminum Cap on 5/8" X 34" rebar.

N81°E 97.52' to set nail & tag in S. side 14" W. Pine  
S61°E 111.29' to set nail & tag in NE. side 8" twin W. Pine  
West 98.38' to set nail & tag in N. side 5", 5", 10" triple Cherry  
S33°W 50.57' to set nail & tag in E. side 6" Cherry  
Set blue Carsonite post with location tag 1' Southwest

Signed by:

Surveyor's Michigan License No.:

46659

Date:

4-1-2013

