

\$7.00
\$2.00

JAN 23 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
KENT COUNTY REMONUMENTATION

For corners in

Kent
(County)

Located in:

Corner Code #

1. Public Land Survey T 5N R 12W B-4
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. , Recorded Plat
5. Private Claims

I, Randy Kolehhouse, in a field survey on March 14 19 95, do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B-4 This corner was not originally set by the G.L.O.

1984 L.C.R.C. #4138

Medema, Van Kooten & Assoc.

Set RR Spike in Root of 24" Maple by
Int. of 1/4 Lines

P.A. 345 1990 KENT COUNTY

PEER APPROVED 8/24/95

CHAIRMAN Randy Kolehhouse

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-4 Found a railroad spike in root of 28" Maple as set by Medema, Van Kooten & Assoc. per L.C.R.C. #4138. Railroad spike is 0.6 North and 0.8 West of intersection of 1/4 lines. Accepted railroad spike as center section.

L.C.R.C. #4138

Sq. spike in E side 24" Maple N 2.45'
Sq. spike in E side 20" Oak S-SE 36.43'
Sq. spike in S side 10" Maple E 6.46'
E & W fence line

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-4 Could not set monument in tree root. Left railroad spike in place.

Sq. spike in E side 24" Maple N 2.45'
Sq. spike in E side 20" Oak S-SE 36.43'
Sq. spike in S side 10" Maple E 6.46'
E & W fence line

Signed by Randy J. Kolehhouse

EARTH TECH

Date

12/22/95

Surveyor's Michigan License No. 25854

Seg 2

REG. OF DEEDS

8878

Register of Deeds Stamp & File Number

95 DEC 28 PM 2:18

STATE OF MICHIGAN
COUNTY OF KENT
RECEIVED FOR RECORD

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	6	5	4	3	2	1						
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

