

JAN 23 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
 Filing Requirement of Act 74, Mich. P.A. 1970  
 KENT COUNTY REMONUMENTATION

For corners in

Kent  
 (County)

Located in:

Corner Code #

1. Public Land Survey T 5N R 12W B-8  
 T \_\_\_\_\_ R \_\_\_\_\_  
 T \_\_\_\_\_ R \_\_\_\_\_  
 T \_\_\_\_\_ R \_\_\_\_\_
2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ Seg. 1
3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

STATE OF MICHIGAN  
 COUNTY OF KENT  
 RECEIVED FOR RECORD  
 95 OCT 31 AM 9:00  
 REG. OF DEEDS  
 8730

Register of Deeds Stamp & File Number

I, Randy Kolehouse, in a field survey on March 14 19 95, do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B-8 This corner was not originally set by the G.L.O.

1901-1960 Survey Notes  
 1966 Wit. Map  
 1973 L.C.R.C. #593

Williams & Works  
 K.C. Surveyor  
 Exxel Engineering

Stake & Stone Set at Int. of 1/4 Lines  
 Iron  
 Set 1/2" Iron by Previous Wit.  
 (K.C. Surveyor Wit. Map - 1966)

P.A. 345 1990 KENT COUNTY

PEER APPROVED 8/24/95

CHAIRMAN Randy Kolehouse

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-8 Found a 1" iron pipe 2' South of the C/L of 88th Street. Per L.C.R.C. #593 as reset by Exxel Engineering using K.C. witness map. Iron is 0.2' North and 0.3' East of intersection of 1/4 lines. Measurement of East to E 1/4 checks Williams & Works records within 0.2'. Accepted 1" iron as Center Section.

L.C.R.C. #593

Nail in face 12" beech SW 46.95'  
 SE cor. hse. fndn. NW 82.27'  
 Nail in face P. pole North 31.10'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-8 Replaced the 1" iron with a standard 4" x 30" Kent County Monument

Nail & K.C. remon. tag in E side P. pole N 10° E 31.56'  
 Nail & K.C. remon. tag in SW side 18" Maple N 55° W 93.64'  
 Nail & K.C. remon. tag in SE side 16" Beech S 65° W 48.02'  
 SE corner hse. fndn. N 45° W 82.27'

Signed by Randy J. Kolehouse  
 EARTH TECH

Date 10/23/95

Surveyor's Michigan License No. 25854

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	16	17	18	19	20	21	22	23	24				
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

