AND CODNED DECORDATION CERTIFICATE

4 L		WMISSION	Filing Requiremer	nt of Act 74, Mich. P.A. Y REMONUMENTATION	1970
-or c	Kont	nty)	·	orner Code #	STATE CEIVI
1.	Public Land	Survey	T R	E-2	IG 28 AM
3. I	Property Cor in Section Miscellaneou Property in S	S S	_ T R		8585 5 Register of Deeds Stamp & File Number
4. 5.	_ot No Private Clain	Recorded	Plat		A B C D E F G H J J K L
menti in the Land 4 and Decre	ereby certify oned in lines current man Management 5 above we se of a Cour as expresse S. Not mo	that under requirem 1 and 2 above were in ual of survey instruction by a decree of a Core in conformance will tof Law; established below:	ield survey onApril 14 ents of P.A. 74 Michigan P. n conformance with regulations ons of the United States Depa court of Law and/or that the cor th the rules of the Michigan Bo d, re-established, monumente all In the same town and ran	A. of 1970, the corner p and rules therefore as requirement of the interior, Burea mer points mentioned in line pard of Land Surveyors or ad, re-monumented, recover	oints suired sau of es 3, 7 by a suired suired suired sau of es 3, 7 by a suired suire
A.	Descriptio	n of óriginal monum	ent and accessories and/or	subsequent restoration:	
E-2	1831 1961 1965 1973 1978 1980 1988	G.L.O. Notes Wit. Map Wit. Map L.C.R.C. #497 L.C.R.C. #1143 L.C.R.C. #1533 L.C.R.C. #4654	Mullett K.C. Surveyor K.C. Surveyor Spicer Exxel Engineering Exxel Engineering Olson, Meyers & May	3/4" Iron in Mon, Box Replaced 3/4" Iron in i	P.A. 345 1990 KENT COUNTY PEER APPROVED 5/25/95 CHAIRMAN Face Mon. Box w/Standard K.C. Mon.
	This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Exxel Engineering on 12/16/80 and was recorded per L.C.R.C. #1533.				
В.	Description of corner evidence found and/or method applied in restoring or reestablishing corner:				
E-2	Found standard Kent County Monument in monument box at the C/L of Ivanrest Avenue running N-S and 64th Street running E-W as set by Exxel Engineering in place of a 3/4" iron they found in a monument box which checked L.C.R.C. #497 and Wit.				

L.C.R.C. #1533

L.C.R.C. #4654

NW cor hae findin (.5' above ground) S47°E 90.41'. PK Nail & tag on top of wood guard rail post S42°W 47.88° PK Nail & tag on top wood guard rail post N63°W 54.38'

NW cor hise findin (1/2' above ground) S 47 E 90.41' PK nail & K.C. Remon tag on top of wood guard rail post S 42 W 47.88' PK nail & K.C. Remon tag on top of wood guard rail post N 63 W 54.38' Nail & tag in SW sde 20" Ash (6' above ground) N11°W 117.15' Nail & K.C. Remon tag in SW sde 22" Ash (6' above ground) N 11 W 117.15' On C/L bit rd N-S-W

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Ç. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Standard Kent County Monument

Surveyor's Michigan License No.

NW cor. hse. fndn. (1/2' above ground) S 47° E 90.41'

P.K. nail & K.C. remon, tag on top of guard rail post S 42° W 48.03'

P.K. nail & K.C. remon. tag on top guard rail post N 63° W 54.46'

Nail & K.C. remon. tag on SW side 22" Ash (6' above ground) N 11° W 117.15'

25854

Nail & K.C. remon. tag on N side P. pole N 80° E 26.82'

Signed by

KOLEHOUSE