

\$7.00 SEP 18 1995
\$2.00 COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
KENT COUNTY REMONUMENTATION

For corners in

Kent
(County)

Located in:

Corner Code #

- | | | | |
|---------------------------------------|-------------|--------------|------------|
| 1. Public Land Survey | T <u>5N</u> | R <u>12W</u> | <u>G-6</u> |
| | T _____ | R _____ | _____ |
| | T _____ | R _____ | _____ |
| | T _____ | R _____ | _____ |
| 2. Property Controlling
in Section | S _____ | T _____ | R _____ |
| | S _____ | T _____ | R _____ |
| 3. Miscellaneous
Property in Sec. | S _____ | T _____ | R _____ |
| | S _____ | T _____ | R _____ |

REG. OF DEEDS

95 AUG 28 AM 10:51

STATE OF MICHIGAN
COUNTY OF KENT
RECEIVED FOR RECORD

8609

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Randy Kolehhouse, in a field survey on April 11, 19 95, do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-6	1831	G.L.O. Notes	Mullett	Set Post
	N/A	Wit. Map	K.C. Surveyor	Monument Box
	1974	L.C.R.C. #765	Exxel Engineering	Found 1/2" Iron in Mon. Box
	1981	L.C.R.C. #1637	Nederveld & Jonker	Found 1/2" Iron in Mon. Box/Set K.C. Monument
	1988	L.C.R.C. #4609	Olson, Meyers & May	K.C. Monument

P.A. 345 1990 KENT COUNTY

PEER APPROVED 5/25/95

CHAIRMAN Randy Kolehhouse

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Nederveld & Jonker and was recorded per L.C.R.C. #1637.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- G-6 Found standard Kent County Monument on C/L of Byron Center Avenue running N-s and on tree line running West per L.C.R.C.'s #1637 and #4609 as set by Nederveld & Jonker in place of a 1/2" iron they found which checked L.C.R.C. #765.

L.C.R.C. #1637

L.C.R.C. #4609

Centerline N.H. S0°W 23.32'
NE cor. catch basin rim S45°W 29.67'
NW cor. catch basin rim S40°E 28.82'
Face curb East 21.53'

C/L M.H. S 0 W 23.32'
NE cor C.B. rim S 45 W 29.67'
NW cor C.B. rim S 40 E 28.82'
Face curb E 21.53'
Nail & K.C. Remon tag in W sde 12" Pine N 40 E 65.84'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- G-6 Standard Kent County Monument

Nail & K.C. remon. tag on W side 12" Pine N 40° E 65.84'
C/L M.H. South 23.32'
NE cor. C.B. S 45° W 29.67'
Face curb East 21.53'
NW cor. C.B. S 40° E 28.82'

Signed by

Randy J. Kolehhouse
EARTH TECH

Date

8/21/95

Surveyor's Michigan License No. 25854

