

SEP 15 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
KENT COUNTY REMONUMENTATION

For corners in

Kent (County)	Located in:	Corner Code #
1. Public Land Survey	T <u>5N</u> R <u>12W</u>	<u>G-12</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

STATE OF MICHIGAN
STAFFORD COUNTY
RECEIVED FOR RECORD
SEP 28 1995
8615

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Randy Kolehouse, in a field survey on April 12 19 95,
do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required
in the current manual of survey instructions of the United States Department of the interior, Bureau of
Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3,
4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered,
found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-12 1831	G.L.O. Notes	Mullett	Set Post
1963	Wit. Map	K.C. Surveyor	Iron in Concrete
1974	L.C.R.C. #960	Don Ratekin	Found 1/2" Iron Pipe in Mon. Box
1981	L.C.R.C. #1647	Nederveld & Jonker	Found 1/2" Iron Pipe in Mon. Box/Set K.C. Monument
1988	L.C.R.C. #4604	Olson, Meyers & May	K.C. Monument

P.A. 345 1990 KENT COUNTY

PEER APPROVED 5/29/95
CHAIRMAN Randy Kolehouse

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Nederveld & Jonker on 3/5/81 and was recorded per L.C.R.C. #1647.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-12 Found standard Kent County Monument in monument box 1.5' West of C/L of Byron Center Avenue running N-S and on C/L
of tree row E-W per L.C.R.C.'s #1647 and #4604 as set by Nederveld & Jonker in place of a 1/2" iron pipe they found in
monument box which checked L.C.R.C. #960 and K.C. Surveyor's Wit. Map (1963).

L.C.R.C. #1647

L.C.R.C. #4604

Nail & Remon. tag on W. side T. pole S20°E 73.62'
Nail & Remon. tag on S. side 44" Oak N85°W 51.56'
Nail & Remon. tag on S. side T. pole N35°E 54.90'
SE corner house found. N35°W 111.21'

Nail & Remon tag on W sde T pole S 20 E 73.62'
Nail & Remon tag on S sde 46" Oak N 85 W 51.56'
Nail & Remon tag on S sde T pole N 35 E 54.90'
SE cor hse fndn N 35 W 111.21'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence
of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-12 Standard Kent County Monument

SE cor. hse. fndn. N 35° W 111.24'
Nail & K.C. remon. tag on W side T. pole S 20° E 73.62'
Nail & K.C. remon. tag on S side 44" Oak N 85° W 51.49'
Nail & K.C. remon. tag on S side T. pole N 35° E 54.85'



Signed by Randy J. Kolehouse
EARTH TECH

Date 8/21/95

Surveyor's Michigan License No. 25854