

JAN 23 1996

LAND CORNER RECORDATION CERTIFICATE
COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970
KENT COUNTY REMONUMENTATION

For corners in

Kent (County)	Located in:	Corner Code #
1. Public Land Survey	T <u>5N</u> R <u>12W</u>	<u>H-10</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	<u>Seg-1</u>
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Randy Kolehouse, in a field survey on April 7 19 95, do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

H-10 This corner was not originally set by the G.L.O.

1914-1927 Survey Notes
1978 L.C.R.C. #1201

Williams & Works
Nederveld & Jonker

Found and Accepted Iron
Found and Accepted 1" Iron

P.A. 345 1990 KENT COUNTY
PEER APPROVED 8/24/95
CHAIRMAN Harry Kube

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-10 Found 1" iron pipe 4' West of C/L of Celery Avenue per L.C.R.C. #1201. Measurements to the E 1/4, W 1/4 and N 1/4 check Jonker Land Surveys $\pm 0.1'$. Measurements to the S 1/4 check Jonker Land Surveys $\pm 0.5'$. This iron appears to be 10' M/L West of iron used by Williams & Works' 1914-1927 survey notes (iron not found). This iron is 0.1' North and 0.2' West of the intersection of 1/4 lines. Accepted iron as Center Section.

L.C.R.C. #1201

Nail in N side P. pole East 35.27'
SW cor. hse. fndn. N 70° E 71.35'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-10 Replaced iron with a standard 4" x 30" Kent County Monument

Nail & K.C. remon. tag in W side 24" Maple N 25° E 66.48'
Nail & K.C. remon. tag in NE side 48" Maple N 30° W 45.57'
PK nail in W end 18" Clump S 75° W 18.36'
Nail in N side P. pole East 35.27'
SW cor. hse. fndn. N 70° E 71.35'

Signed by Randy J. Kolehouse
EARTH TECH

Date 10/25/95

Surveyor's Michigan License No. 25854

STATE OF MICHIGAN
COUNTY OF KENT
RECEIVED FOR RECORD
95 OCT 31 AM 9:02
REG. OF DEEDS
Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	5	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	16	17	18	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

