SEP 1 3 1995

Ford	corners in	MAISSICH	Filing Requiren	nent of Act 74, Mich. P., NTY REMONUMENTATION	A. 1970		<b>S</b>
	Kent (Count	у)	Located in:	Corner Code #			STATE COUNT RECEIVE
1.	Public Land S	Gurvey	T_5N R_12W T R T R	H-13			MA 82 WHO YES
i	Property Cont in Section Miscellaneous	S	- 1 I I			8623	10: 25 10: 25 10
	Property in Se		TR		Regist	er of Deeds Stam	o & File Number
4. l 5. l	Lot No	, Records	ed Plat		<del></del>	A B C D É F	G K   J K L
					2	6 5 4	3
l	Randy Koleh	ouse in a	a field survey onApril 7	, 19	95 4	7 8 9	10 11 12
do he menti in the Land 4 and Decre	ereby certify to toned in lines 1 courrent manu Management of 5 above were ee of a Court	that under require and 2 above were al of survey instructor or by a decree of a e in conformance v of Law; establish	ments of P.A. 74 Michigan in conformance with regulation of the United States De Court of Law and/or that the with the rules of the Michigan ned, re-established, monume	P.A. of 1970, the comer ons and rules therefore as re- partment of the interior, Bu comer points mentioned in Board of Land Surveyors	r points serequired 6 areau of lines 3, . 7 or by a	17 16 19 20 21	15 14 13 22 22 23 24
NOTE		e than 4 corners,	all in the same town and i	range, may be recorded	10		27 26 25
		certificate.	. : 1 ·		12		35 36
A.	Description	of original monu	ment and accessories and	or subsequent restoration			
H-13	1963 1973 1974 1981 1991	G.L.O. Notes Wit, Map L.C.R.C. #424 L.C.R.C. #960 L.C.R.C. #1702 L.C.R.C. #6325	L. Lyon K.C. Surveyor Medema, Van Kooten Don Retekin Williams & Works Chris Marschall roved by the Kent County F	Found 3/ Found 3/ K.C. Mon	PEE Iron CHA 4" Pipe 4" Pipe/Set K. nument	.C. Monument	5/25/95 mg//Lupe
	on 2/23/81 a	and was recorded	per L.C.R.C. #1702.	iononamentation i ser a	oup and mo	turnerned by with	ALIES OF ANOTHER
В.			ce found and/or method ap	•	•		
H-13	L.C.R.C.'s #	lard Kent County 1702 and #6325 a ne Town line.	Monument on the C/L of 10 as set by Williams & Works	8th Street running E-W and per L.C.R.C.'s #424 and	nd 15' East of #960 and K.C	f C/L road running C. Surveyor's Wit.	South per Map. This
		L.C.R.C. #170	2	L.C.R.C.	#6325		
		Remon. tag in NE e. #1995 (Brick) N	Side 18" Maple N 80°W 191 25°E 93.45'	.87' SW Corner Hse 199 N 27 E 93.36' Nail & Tag S side T Nail & Tag S side P Nail & Tag NE side	win 12" Walnı .P. N 70 W 18	ut N 80 E 149.93' 32.96'	rick
	The selected of the position	d location is accep on of the original c	ted by me and is generally a	accepted by professional	surveyors as	the best available	evidence
C.	Description	of monument for	corner and accessories es	tablished to perpetuate	locating the p	position of the co	mer:
H-13	"X" cut SW cor Nail & I Nail & I Nail & I	r. hse. #1995 108t K.C. remon. tag or K.C. remon. tag or K.C. remon. tag or	ent nc. ret. wall N 77° E 81,90' h 4' above ground (brick) N a 8 side12" Walnut N 80° E a 6 side P. pole N 70° W 182 a NE side 22" Maple N 81° V a SW cor. wood fence post 8	149.93' 2.96' V 191.76'		KOL	F M/C//GANDY J. EHOUSE LAND RVFYOR No. 5854
Signe	d by	andy	y feeline	Date	8/25/	95 " " " " " "	AND SUKE
Surve	yor's Michigar	/EAR n License No	25854				