SEP 1 0 1995

Surveyor's Michigan License No.

25854

For	corners in		Filing I	Requireme	econdation Certifica nt of Act 74, Mich. P.A. 19 TY REMONUMENTATION	970		
	Kent	unty)	Located in:		Corner Code #	RECOAL STATE		
	(00							
1.	Public Land	d Survey	T <u>5N</u> R		<u>J-13</u> ·			
			TR TR					
	Duamantu C		TR_					
	Property Co in Section	-	STR STR	7.7		86/12 S S S		
	Miscellane		3TR_			CUTO		
i	Property in	Sec.	STR_			Register of Deeds Stamp & File Number		
4.	ot No.	, Rec	orded Plat	7				
		ims		2 1	· · ·	A B C D E F G H I J K	L	
			: -1			2 5 4 3 2	1 –	
				. 3		3	L	
l,	Randy Kol	ehouse,	in a field survey on	April 6	19 95	_, 4 7 8 9 10 11	 2—	
do h	ereby certif	y that under req	uirements of P.A. 74	Michigan P	A. of 1970, the corner poir	nts 5	_	
in the	current ma	is I and 2 above wanual of survey ins	vere in conformance wit structions of the United	n regulations States Depa	and rules therefore as requirers and rules the and rules the interior. Bureau	of 6 18 17 16 15 14 1	3	
Land	Manageme	nt or by a decree	of a Court of Law and/o	r that the co	rner points mentioned in lines	3, 7	_	
					oard of Land Surveyors or by ed, re-monumented, recovere		4 I	
	as express		bilotted, re-established,	monumente	ed, re-monumented, recovere	9	_	
NOTE	: Not m	ore than 4 corn	ers, all in the same to	wn and rar	ige, may be recorded	10 29 28 27 26 2	5—	
	on thi	s certificate.		5.		11	_	
Α.	Descripti	on of original me	nument and accesso	ries and/or	subsequent restoration:	12 31 32 33 34 35 3	6	
J-13	1817	G.L.O. Notes	:	i i	•	P.A. 345 1990 KENT COUNTY		
0-10	1951	Wit. Map	L. Lyon K.C. Surv	evor	Set Post 1" Iron	PEER APPROVED 6/27/95		
	1966	Wit. Map	K.C. Sun		1" Iron	CHAIRMAN TOUR OLL	1	
	1971 L.C.R.C. #4		Don Rate		Found 1" Pipe/Ra		14	
	1981	L.C.R.C. #170			Found 1" Iron/Set			
	1992	L.C.R.C. #634			K.C. Monument			
	This corn on 2/19/8	er was originally 1 and was record	approved by the Kent led per L.C.R.C. #170	County Rer	monumentation Peer Group	and monumented by Williams & Works		
В.	Description	on of corner evic	dence found and/or m	ethod appl	ied in restoring or reestabli	ishing corner:		
J-13	Found sta	andard Kent Cour orner shown in K.	nty Monument at the C	L of 108th	Street running E-W. This po	oint is on the Town line 8.56' West of by Williams & Works in place of a 1"		
	non they i	L.C.R.C. #1701			L.C.R.C. #634			
	CE Con II		:	2				
		lse. Fnd. N 55°E t West 1.81 & So		1	Nail & Tag E Side Twin 12"	Elm N 33 W 29.18'		
	*****	11000 1.01 & 001		Nail & Tag SW Side 10" Cherry S 49 E 40.92 Spike SE Side 12" Ash S 50 W 45.42'				
					Spike W. Side 14" Ash S 14			
			•		SE corner Hse. Fndn. N 55 i			
			•		DAA C.P.C. capped iron N 9			
					Well point West 1.81 and So			
	The selected location is accepted by me and is of the position of the original corner.			enerally acc	cepted by professional surve	eyors as the best available evidence		
c.	Description	on of monument	for corner and access	sories estal	hlished to perpetuate locati	ing the position of the corner:		
J-13		Kent County Mon		, , , , , , , , , , , , , , , , , , , ,	onstied to perpetuate locati	ing the position of the corner:		
		-				OF MICHINA		
			g on E Side Twin 12" E			DANDY		
	Nail	& K.C. remon. tag	g on SW Side 10" Che	rry S 49 E 4	0.92'	RANDY J. KOLEHOUSE		
	SE corner hse, fndn. N 55 E 99.05' Nail & K.C. remon, tag on S side P. po			3° E 125 26	5'	LAND		
			July 2 and 1 a polo in 1	:20.20	•	SURVEYOR No.		
		<i>^</i>	•			25854		
	. /	1/10	QVII		- 0	10. 1 The Olive SURVE sint		
Signe	i by	unay_	7 coupe	-	Date 8 /	4/95 CARD CARD		
		/ 4	MKIN IECH	1				