SURVEY & REMONUMENTATION

APR 27 1995

COMMISSION

Surveyor's Michigan License No. 12579

STATE OF HIGHER NO COUNTY OF HENT RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE 91, DEC 28 PM 2: 15

COMMISSION	Filing Requirem	ent of Act 74, Mich. P.A.	1970
For corners in		•	1970 Lini James
Kent	Located In:	Corner Code ##	
(County)	Located III.	Corner Code -74	REG. OF DEEDS
	EN 121	L-10	1 to- w.
1. Public Land Survèy	т <u>5N</u> R 12W	L-10	
	T R		
	T R		
	T R		
2. Property Controlling S	T R T R		PM O O O
in Section S	TR		7926
	T R		Register of Deeds Stamp & File Number
·	T R		hegister of Deeds Statilp & File Nutiber
ribperty in dec.		<u> </u>	
4. Lot No	d Dist		
5. Private Claims	1 1 1		A B C D E F G H I J K L M
5. Private Ciamis			2 6 5 4 3 2 1 1
		•	3 1 1 1 1 1 1 1
	'		
Douglas W. Bonnema in a fi	Nov. 1	6 94	* 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
do hereby certify that under requiremen	PID SUIVEY DII	. 17	-
do hereby certify that under requirement in lines 1 and 2 above were in conform	nance with regulations and re	des therefore as required in the	6 18 17 16 15 14 13
current manual of survey instructions of	of the United States Departme	nt of the Interior, Bureau of Lar	nd 7
Management or by a decree of a Court of	f Law and/or that the corner po	pints mentioned in lines 3, 4 and	15 8 19 20 21 22 23 24
above were in conformance with the rul	es of the Michigan Board of La	and Surveyors or by a Decree of	ta alīlīlīlīlīlīlīl
Court of Law; established, re-establi	ished, monumented, re-mon	umented, recovered, found a	as []]]]
expressed below:			10 30 29 28 27 26
NOTE: Not more than 4 corners,	all in the same town and i	ange, may be recorded	11
on this certificate.			12 31 32 33 34 35 36
•			13
A. Description of original monume	ent and accessories and/o	r subsequent restoration:	
Since this is not a g	overnment corner th	ere is no G.L.O. in	formation.
-			
Williams & Works 1898		at the intersection	or 1/4 lines
Williams & Works 1907			
Face of 10" Ash South	28.85		
Exxel Engineering 197	8 found and used t	he gas pipe and wit:	nesses
			·
 B. Description of corner evidence 	found and/or method app	lied in restoring or reestabl	ishing corner:
Found 1/2" gas pipe			
Center of 30" Ash Sou	th 29.24'	•	
	, i		
We calculate the pipe	is 1.1'+ North and	1 1.2'+ East of the	intersection of the 1/4 lines.
me current the pripe			
The selected location	is accepted by me	and is generally ac	cepted by professional
surveyors as the best	available evidence	e of the position of	the corner.
	: '		
		P.A. 3	345 1990 KENT COUNTY
		PEER	APPROVED 10/12/97
	•		
		CHAI	RMAN Janes Kuple
•			sing she annisian of star annual
C. Description of monument for co	orner and accessories esta	ablished to perpetuate local	ting the position of the corner:
Replaced 1/2" pipe wi	th 4" x 30" Kent Cr	ounty Cast Iron Mon	
Nail & KC tag in N'ly	sde 13" Ash	\$70°E 87.50'	
Nail & KC tag in NE s	de 12" W Cherry	S42°E 37.41'	
Nail & KC tag in W sd		S05°E 29.24'	
Mail of No tay III W Su	cdo 10" Manla	S70°W 20.14'	
Nail & KC tag in N'ly	sue io mapie	570 W 20.14 S87°W 31.68'	
Nail & KC tag in S'ly	Sae 14" birch		
Nail & KC tag in E sd	e 8" w. therry	NOO°E 8.00'	BONNEMA
N and S fence		East 1.4'	SURVEYOR Z
			₹ NO. / ₹
1	:	•	12570