

## COMENTATION

JAN 2 3 1996	LAND CORNER RECORDATION CERTIFICATE
40	Filing Requirement of Act 74, Mich. P.A. 1970

		Filing Requirem	ent of Act 74, Mich. P.A. 1970	
Ford	corners in COM	MISSION KENT COUN	NTY REMONUMENTATION	المستورث وسنع أ
	Kent (County)	Located in:	Corner Code #	
1.	Public Land Survey	T <u>5N</u> R <u>12W</u> _ T R T R	D-4	FOR RECORD OF DEEDS
		s T R	Jag. 2	8884
		STR	<del>- /  </del>	
		STR STR	Re	egister of Deeds Stamp & File Number
		corded Plat		A B C D E F G H I J K L
				2 6 5 1 1 3 2 1 1 3
do h ment in the Land 4 and Decre found	ereby certify that under re- ioned in lines 1 and 2 above a current manual of survey in Management or by a decrea d 5 above were in conforma ee of a Court of Law; est d as expressed below:	astructions of the United States De of a Court of Law and/or that the once with the rules of the Michigan ablished, re-established, monume	P.A. of 1970, the corner points ons and rules therefore as required partment of the interior, Bureau of corner points mentioned in lines 3, Board of Land Surveyors or by a nited, re-monumented, recovered,	4 7 6 9 10 11 12 12 15 14 15 14 15 14 15 10 10 10 10 10 10 10 10 10 10 10 10 10
NOT	E: Not more than 4 corr on this certificate.	ners, all in the same town and r	range, may be recorded	11 2 31 32 33 34 35 36
A.	Description of original n	nonument and accessories and	or subsequent restoration:	13
D-4	•	es Williams & Works es Williams & Works	Found & Accepted Leaded Set RR Spike at Int. of 1/4 L Set "T" Iron per Wit. for RR soc. Found "T" Iron within 1" of T	ines
			P.A. 34 PEER CHAIR	45 1990 KENT COUNTY APPROYED A/24/95 MAN Famy of Lubere
В.	Description of comer ev	idence found and/or method ar	oplied in restoring or reestablishi	
D-4	Found "T" iron 5.0' East of true 1/4 line intersection	of C/L of Homerich Avenue per L	C.R.C. #151 as accepted by MVh10' East of the intersection of 1/4	K which they found to be within 1' 4 lines. Measurements E-W & N
	L.C.R,C. #151			

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-4 Replaced "T" iron with a standard 4" x 30" Kent County Monument

> Nail & K.C. remon. tag in W side 12" Ash S 12° E 81.44' Nail & K.C. remon. tag in S side P. pole N 60° W 38.40'

> > 25854

SE corner hse. fndn. N 70° W 108.25'

SE cor. hse. W-SW 108.25' NE cor. garage NW 147.03' SW cor. garage NE 94.08'

Surveyor's Michigan License No. \_

NE corner garage fndn. N 42° W 147.15'[

SW corner garage fndn. N 63° E 93.87'

Signed by\_ EARTH TECH

RANDY J. **KOLEHOUSE** LAND SURVEYOR 25854 LAND SURVEY 25854

E OF MICK

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1871 REVISED MAY 14, 1975 REVISED JAN.. 1883