

SURVEY & REMONUMENTATION

MAR 03 1998

KENT COUNTY REMONUMENTATION

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
KENT COUNTY
(County)

Located In:

Corner Code #

1. Public Land Survey

T___ R___
T___ R___
T___ R___
T___ R___

2. Property Controlling
in Section

S35 T6N R9W
S___ T___ R___

3. Miscellaneous
Property in Sec.

S___ T___ R___
S___ T___ R___

Wit. Mon. on
E-W 1/4 line

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Kirk Breitels, in a field survey on July 30, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1996---Survey---Prein & Newhof---Established 1/8 corner on E-W 1/4 line East of the W 1/4 corner of Sec. 35

P.A. 345 1990 KENT COUNTY

PEER APPROVED 8/28/97

CHAIRMAN Harry Huhner

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Established the 1/8 corner on the E-W 1/4 line East of the W 1/4 corner of Sec. 35.
Found Rerod 0.0' N. & 0.05' E.
Found Sq. Iron 0.1' W. & 0.2' S.

See LCRC # 10069 for Central 1/4 corner (J-12) of Sec. 35

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Harrison Monument with witness cap at 1/8 corner described above, removed other 2 Irons found.

Nail & KC Remon. tag N. side fence corner post S90°W 40.42'
Nail & KC Remon. tag N. side 30" Maple N60°W 33.73'
Nail & KC Remon. tag NE side 12" Elm N15°W 82.89'
Nail & KC Remon. tag NE side 18" Oak S55°E 31.47'
Nail & KC Remon. tag SE side 12" Cherry N55°E 27.89'
Old fence to East is 4' South ±, New fence to West is 2' South ±
C/L N-S asphalt road is West 6' ±

Signed by

Kirk Breitels

Date

9/22/97

Surveyor's Michigan License No.

30077

"other" code
11

REG. OF DEEDS

97 OCT 14 AM 10:32

STATE OF MICHIGAN
COUNTY OF KENT
RECEIVED FOR RECORD

10070

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

