

OCT 28 1994

STATE OF MICHIGAN
COUNTY OF KENT
RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

JUL -5 PM 3:12

For corners in
KENT COUNTY
(County)

Located In:

Corner Code #

1. Public Land Survey T ___ R ___
T ___ R ___
T ___ R ___
T ___ R ___
2. Property Controlling S 2 T 6N R 10W
in Section S ___ T ___ R ___
3. Miscellaneous S ___ T ___ R ___
Property in Sec. S ___ T ___ R ___

Other Code

#1

Wit. Mon. on

on E. line

Sec. 2

Timothy J. Bond
REG. OF DEEDS

6950

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, William R. Byl, in a field survey on Feb. 18, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Post set at meander corner on right side of Grand River per GLO survey

No other information available from the County Surveyor's Office, other surveying firms or any other sources.

P.A. 345 1990 KENT COUNTY
PEER APPROVED 3/24/94
CHAIRMAN *Harry Stuber*

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Did not find meander corner as set per GLO survey

No evidence or occupation at the river. Set Kent County Reference Monument near the NE'y bank of the Grand River by projecting the Section line as used in surveys by Exxel Eng. and Williams & Works South to the river.

Monument is 10.7' East of a straight line between the NE & SE corners of Section 2.

Corner "G" on recorded survey of Sections 1 & 2-6-10
Recorded survey L265 P21

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Kent County Reference Monument
Top of steel fence post (alone)
Nail & KC Remon. tag E. corner RR tie fence post
Nail & KC Remon. tag NW side Twin 10" Maple
Nail & KC Remon. tag SW side 10" Maple
Fence running NE-SW is Northwest 9.5'
Top of bank is South 35' m/l
NE'y bank of the Grand River is South 65' m/l

S35°W 30.73'
N00°E 18.62'
N50°E 60.58'
S40°E 77.70'



Signed by *W. R. Byl*
Surveyor's Michigan License No. 23502

Date 06/27/94