

FEB 14 1997

KENT COUNTY REMONUMENTATION

**COMMISSION LAND CORNER RECORDATION CERTIFICATE**

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
**KENT COUNTY**  
(County)

Located In:

Corner Code #

1. Public Land Survey

T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_

#13

2. Property Controlling  
in Section

S 26 T 8N R 11W  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

Wit. Mon. on  
E. line Sec. 26

3. Miscellaneous

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

Property in Section

REG. OF DEEDS

*Lucy Bond*

96 MAR 20 AM 8:59

STATE OF MICHIGAN  
COUNTY OF KENT  
RECEIVED FOR RECORD

**9111**

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, **Kirk Breitels**, in a field survey on **Jan. 25**, 19 **96**

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

1837	GLO	Whitcomb	Set Meander Post 39 chains North of the E 1/4 corner of Sec. 26
1992	LCRC #6616	Marschall	Set Kent County Witness Monument on E. line of Sec. 26.

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented (Witness Monument) by Chris Marschall on 10/27/92 and was recorded per LCRC #6616.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
Found Standard Kent County Witness Monument per witnesses from above LCRC as set by Chris Marschall.

**LCRC #6616**

Nail & KC Remon. tag SW side Fence Post	S51°E 116.74'
Nail & KC Remon. tag SW side 6" Walnut	S51°E 130.63'
Nail & KC Remon. tag SW side 4" Hackberry	S58°E 87.31'
Nail & KC Remon. tag SW side 8" Oak	N42°W 77.56'
NE cor. hse.	N49°W 415.12'
SE cor. hse.	N60°W 438.31'
Top of bank is NE 1.5'±	
River bank is NE 25'±	

P.A. 345 1990 KENT COUNTY

PEER APPROVED 3/7/96

CHAIRMAN

*Harry Huber*

The selected location is accepted by me and is generally accepted by professional surveyors as the best available location of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**Standard Kent Co. Witness Monument**

Nail & KC Remon. tag SW side Fence Post	S51°E 116.78'
Nail & KC Remon. tag SW side 6" Walnut	S51°E 130.68'
Nail & KC Remon. tag SW side 4" Hackberry	S58°E 87.28'
Nail & KC Remon. tag SW side 8" Oak	N42°W 77.56'
NE cor. hse.	N49°W 415.12'
SE cor. hse.	N60°W 438.36'
Top of bank is NE 1.5'±	
River bank is NE 25'±	



Signed by

*Kirk Breitels*

Date

2/6/96

Surveyor's Michigan License No. **30077**