SURVEY & REMONUMENTATION

MAY 0 9 1996

LAND CORNER RECORDATION CERTIFICATE

	11	
	(Y.1"	
$R[\cdot]$		

Ear.	CORNOLO	4	

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

SOLON TOWNSHIP

ŔĮ	(
Qq	Et - s	

	Kent	Located In:	Comer Code 77
١.	Public Land Survey	T_10N R 11W	South witness
		T R	monument to F-1
	•	T R	
		TR	ا کا لیام
2.	Property Controlling	S R	Other lade
	in Section	SR	
3.	Miscellaneous	SR	#2
	Property in Sec.	SRR	11 2

.... Recorded Plat

6803Register of Deeds Stainp & File Number

Wallace E. Glaza , in a field survey on July 22 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Lawand/or that the corner points mentioned in times 3/4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decision of a

Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration

No previous history.

5. Private Claims

expressed below:

	Α	В	С	D	E	F	G	11	1 3	ĸ,	ı	M
2		6 -		5	_	4		3]	
3		 	┞	<u> </u>	ļ	ļ						_
4	_	ļ	1_	[8	_	ģ	-	10		٠. إ	ŀ	?
5]	1_	L		ļ	1_			1			-
6		18	<u> </u>	 7		 16 -		15	!	1.	;	3-
7	-	1_	1_		ļ. <u>.</u> .	_	<u>. </u>	1.	1.1			
B	_	 19	<u> </u>	0		21 -		 27		,	2	4
9		1_	<u> </u>	ļ	ļ. <u></u>	ļ.,	.		1 1			<u> </u>
10		30		9		28		2;	j ;		2	5
11		1_	ļ	ļ	ļ	ļ.,	Į.	-		.		ļ ,,
12	-] 31	ļ;	32	ļ	33 ·	Ĺ	38	1	,	3	ß-
13	L	1_		<u>L</u> _	L	.L.	_L.	i.				

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

South witness monument to F-1, Section 4, T10N, R11W, Solon Township, Kent County, Michigan.

Set standard 4 x 30" Harrison Monument 7'± South and 10' East of waters edge of Gilbert Lake on a straight line between the North & corner (mathematical) and the center of Section.

Witness corner is 2791.35' North of center of Section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

South witness monument to F-1 (4" x 30" standard Harrison Monument)

- Nail and tag in N side 30" Maple N70°E 9.44'
- Nail and tag in SE side 14" Pine S50°W 14.34'
- Nail and tag in E side 28" Pine 3) S20°W 17.43'
- Nail and tag in E side 18" Beech 4) 530°W 45.42'
- North-South fence 5) East

Date Glaza and Associates, Inc. Surveyor's Michigan License No. /31592

8-9-93

arvisin JIN 198

GLAZA LAND

SURVEYOR

No.

31592 OLANDS

REC DO