LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u></u> -	LAKE (County)		Located	ln:	Corner Code :##			
1.	Public Land Survey		T	R 13W R R R	X-11, L-11			
2.	Property Controlling in Section	S 36	T . T _	R <u> </u>	- 1, 5			
3.	Miscellaneous Property in Sec.	S S .	T T	R. R				

Register of Deeds Stamp & File Number

- 4. Lot No. _ , Recorded Plat
- 5. Private Claims


. in a field survey on CARL I. KIISKILA JUNE 6 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

K-11 L-11

(NO EVIDENCE OF G.L.O. CORNER, B.F'S, LINE TREES & TOPOGRAPHY, AS CALLED OUT IN THE G.L.O. LINE NOTES; UNLESS NOTED IN ITEM "B" BELOW.)





B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FD. G.BLASS BRASS CAPPED MON. FOR THE NW COR SEC. 36. (GEORGE BLASS #5489 STAMPED ON MON.) CTR. OF E-W GRAVEL ROAD IS 2' NORTH.

L-11 FD 1/2" PIPE FOR THE N1/4 COR FOUND 1/2" PIPE FOR THE NW 1960 WITS. CORNER IS IN INTERSECTION OF SAND/GRAVEL ROADS E-W-S.

SEC. 36. COR FITS RLS. G.BLASS COR. OF THE NEL/4 OF THE NWI/4 R.WETHERELL PS CAP FOR THE SW OF SEC. 36. FD. 4" CONC. MON. COR OF THE NW1/4 OF THE NEI/4 13.56' EAST AS NOTED ON G.BLASS 1972 SURVEY MAP AS THE STANDARD SUBID. OF SECTION PER NW COR OF E1/2 OF GDVT. LOT 1. BLM INSTRUCTIONS, CIR. CF N-S CTR. OF 23' WIDE GRAVEL ROAD IS 3' NORTH.

FOUND 1/2" REROD W/C.COLE & OF SEC. 36. CORNER FITS SAND ROAD IS 3' WEST.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

X-11		L-11				1			5			
FD. BRASS CAPPED CONC. HON.		FD. 1/2" GALV. PIPE.			FD 1/2" GALV. PIPE.			FD. 1/2" REROD W/PS CAP.				
9" W.PINE	N35°W	46.70	POWER POLE	N50°W	36.60,	14" W.OAK	N05°W	38,241	7" N.PINE	N60°W	49.37	
15" W.P1NE	N35°E	43.60	#9" W.OAK	N40°E	45.45	18" MAPLE	N45°E	51.51	5" W.PINE	N25°E	55.91	
POWER POLE	515°E	23.12	#14" W.OAK	525°E	83.97	6" B.OAK	545°¥	34.55	9" J.PINE	S50°W	34.401	
3" W.PINE	540°W	34.29	#17" W.DAK	555°W	50.18	SET CEDAR PO	IST WITH		SET CED POST	W/LDC TAS	BY FD.	
SET CEDAR POST WITH						LOCATION TAG	SOUTH	23.	1/2" REROD V	VRLS CAP	EAST 331	
LOCATION TAG	SOUTH	33.										

FD NAIL, REPLACED WITH 5/8"x 34" REROD WITH PS CAP, \$00°40'49"W 654.24"

= RLS, G.BLASS 1960 WIT.

33981

Carl T Kirkela

12-5-95

Date