

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: <u>Lake</u> (County)	Located In	Corner Code #	
1. Public Land Survey	T _____ R _____		
	T _____ R _____		
2. Property Controlling in Section	S <u>20</u> T <u>19N</u> R <u>11W</u>	<u>4</u>	
	S <u>20</u> T <u>19N</u> R <u>11W</u>	<u>5</u>	
3. Miscellaneous Property in Section	S _____ T _____ R _____		
	S _____ T _____ R _____		
4. Lot No: _____	Recorded Plat: _____		
5. Private Claims: _____			



RECEIVED
 05/05/2014 3:53:21 PM
 LAKE COUNTY, MICHIGAN
 SHELLY MYERS, CLERK/REGISTER/CFO
 RECORDED
 05/05/2014 3:56:18 PM
 LAKE COUNTY, MI
 SHELLY MYERS, REGISTER OF DEEDS
 RECEIPT# 5785, STATION 1
 \$14.00 LAND CORNER



Liber C8 Page 17

Register of Deeds Stamp & File Number

I, Joshua R. Davidson, in a field survey on June 12, 2012 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

4 – NW 1/16 corner section 20

5 – CN 1/16 corner section 20

2002 – Certificate of Survey – File #9922-02
 – R. Wetherell, PS #24624 – 1/2" rebar found – added cap marked PS #24624.

2002 – Certificate of Survey – File #9922-02
 – R. Wetherell, PS #24624 – 1/2" capped iron set marked PS #24624.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

4 – NW 1/16 corner section 20

5 – CN 1/16 corner section 20

Found 1/2" X 18" rebar & cap #24624 per Wetherell, Certificate of Survey. Also found 3/4" pipe 1.5' of unknown origin 5.27' to the Northwest. Accepted found rebar and cap as the best available evidence of the position of the corner and replaced it with a stamped 2" aluminum cap on 5/8" x 34" rebar.

Found 1/2" X 18" rebar & cap # 24624. Replaced it with a stamped 2" aluminum cap on 5/8" X 34" rebar and is accepted as the best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

4 – a stamped 2" Aluminum Cap on 5/8" x 34" rebar

5 – a stamped 2" Aluminum Cap on 5/8" X 34" rebar

N55°E 10.42' to set nail & tag in SE. side 7" Oak
 S45°E 22.70' to set nail & tag in SW. side 15" R. Pine
 S04°W 22.46' to set nail & tag in E. side 16" Oak
 N41°W 38.43' to SE corner of pole barn
 N38°59'W 5.27 to found 3/4" pipe

N22°E 67.31' to set nail & tag in W. side 14" R. Pine
 S77°E 21.76' to set nail & tag in N. side 8" S. Maple
 S62°W 42.85' to set nail & tag in SE. side 26" Oak
 N26°W 60.86' to set nail & tag in NE. side 14" R. Pine

Set blue Carsonite post with location tag 1' Northeast

Set blue Carsonite post with location tag 1' North

Signed by: Joshua R. Davidson
 Surveyor's Michigan License No.: 46659

Date: MAY 5, 2014

