

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Lake _____ Located In _____ Corner Code # _____
(County)

1. Public Land Survey T _____ R _____
T _____ R _____
2. Property Controlling in Section S 14 T 19N R 13W 4
S 13 T 19N R 13W 3
3. Miscellaneous Property in Section S _____ T _____ R _____
S _____ T _____ R _____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Craig W. McVean, in a field survey on May 17, 2001 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

4 - G. Blass - 1960 - Survey Sec. 14.
Set 1/2" iron pipe

3 - G. Blass - 1941 - Survey of sec. 12 & 13.
Shows corner.
- DNR Sur. Proj # 68-31 - C.F. Roser - 1968
Fd. 1/2" iron pipe

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

4 - NW 1/16 cor. sec. 14 -
Fd. 1/2" I.D. Iron pipe with grader blade along side per
Blass 1960. CL of 3- Mile Rd. is 57' N. 1/2" iron pipe accepted
as the best available evidence of the position of the corner.

3 - N1/16 Cor. common to Sec. 14 & 13
Fd. 3/4" Iron rod that fits fence line S&E at proper
calculated position. No evidence of 1/2" pipe. CL of 3- mile Rd.
is S. 215.65' (Blass). 3/4" Iron rod accepted as the best
available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

4 - 1/2" Iron pipe
North 24.23' to Fd. 1/2" rebar
NE 1' to set Blue carsonite post w/ loc. tag
N84°E 23.98' to N&T in N. side 15" B. Oak
N45°E 13.35' to N&T in NW. side 9" J. Pine
N85°W 12.92' to N&T in N. side 11" B. Oak

3 - 3/4" Iron Rod
W. 1' to set blue carsonite post w/ loc. tag
N 29.97' to Fd. 1/2" CIR #24624
N54°E 18.42' to N&T in SE. side 9" R. Maple
N64°W 27.21' to N&T in SW. side 6" R. Maple
S62°W 11.09' to N&T in NW. side 6" R. Maple



Signed by:

Craig W. McVean

Date:

11/26/2001

Surveyor's Michigan License No.: 39088