

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Lake _____ Located In _____ Corner Code # _____
(County)
1. Public Land Survey T 20N R 12W D4
T
2. Property Controlling in Section S T R
S T R
3. Miscellaneous Property in Section S T R
S T R
4. Lot No: _____ Recorded Plat: _____
5. Private Claims: _____

I, Craig W. McVean, in a field survey on Dec. 8, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Table with 13 rows and 13 columns (A-M). Cell (4, D) contains the number 8.

A. Description of original monument and accessories and/or subsequent restoration:

D4 - 1973 - LCRC - L. 2, p. 179 and Rec. Survey L. 1, p. 353 -
C. E. Cole
Set 1/2" rebar at intersection of 1/4 lines
1) 8" J. Pine N60°W 49.30';
2) 8" J. Pine S54°W 64.13';
3) 10" J. Pine S84°E 86.36'
Additional work by DNR Surveyor C. Roser in 1974 -
Add Cedar post with loc. tag
Accepted C. Cole Cor.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D4 - C 1/4 Corner Sec. 8, T20N, R12W
Fd. 1/2" x 18" capped iron #17615.
Centerline of N-S Gravel road is 16' West.
Accepted 1/2" CIR as the best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D4 - Replaced 1/2" CIR with stamped 2" Alum. Cap on
5/8" x 3/4" iron rebar - Buried. Reset cedar post with loc. tag on N. side.
East 33.00' to Fd. 1/2" CIR #17615 and add Blue Carsonite Post with loc. tag.
N61°W 49.29' to set N & T at fd. N & T in SW side 10" J. Pine (#1)
S88°E 86.37' to set N & T at Fd. N & T in N. side 12" J. Pine (#3)
S43°W 63.90' to set N & T in NW side 12" J. Pine (#2)
N5°W 120.98' to set N & T in E. side 12" Oak



Signed by: [Signature]
Surveyor's Michigan License No.: 39088

Date: 10/25/2011