## BURVEY & REMONUMENTATION

APR 2 9 1996

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	ulrement of Act /4, Mich. P.A. 1970	
For corners in Lapeer Located In:Metan	mora Twp Corner Code #	RECEIVED FOR PECORD
1. Public Land Survey T 6N_R_1	LOE L-13	95 OCT -6 PM 1: 15
T R T R		LIBER NO. 005 TAGE NO. 293
<u> T B _</u>		REGISTER OF DEEDS LAPEER SCIENCE MICHIGAN
in Section S T R		LAPEER DR BY C MICHIGAN
3. Miscellaneous       S T R         Property in Section       S T R	l Don	gister of Deeds Stamp & File Number
4. Lot No, Recorded Plat  5. Private Claims		- A B C D E F G H J K L M
<u> </u>		2 -6 -5 -4 -3 -2 3
. Ilyahan V. Vannadus in field aminu an	-mt 20 10 0E	4 7 8 9 10 11 12
I, <u>Huston K. Kennedy</u> , in a field survey on <u>Ai</u> do hereby certify that under requirements of P.A. 74, Michiga in lines 1 and 2 above were in conformance with regulations	an P.A. of 1970, the corner points mentioned	6 18 17 16 15 14
manual of survey instructions of the United States De Management or by a decree of a Court of Law and/or that ti	partment of the Interior, Bureau of Land he comer points mentioned in lines 3, 4 and	8 19 20 21 22 23 24
5 above were in conformance with the rules of the Michiga Decree of a Court of Law; established, re-established, month	an Board of Professional Surveyors or by a amented, re-monumented, recovered, found	9 29 28 27 26 25
as expressed below:  NOTE: Not more than 4 corners, all in the same town	and range, may be recorded	11
on this certificate.  A. Description of original monument and accessor	ica and/ar aubacauant rastarations	13 31 32 33 34 35 36 1
<ul> <li>2.) 1981-Elrich, PS #18986; Survey L.005, Pg.948 - Fnd Pinched Pipe, used same wit as Survey #1</li> <li>3.) 1990-Elrich, PS #18986; Survey L.008, Pgs. 640 &amp; 641 - Fnd Pinched Pipe</li> <li>4.) 1994-Elrich, PS #18986; Survey L.010, Pg.380 - Fnd Pinched Pipe, used same wit as Survey #3</li> <li>B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:</li> <li>1995-Kennedy Survey, Inc Kennedy, P.S. #17623 - Fnd 2" diameter brass cap stamped Oakland County Remonumentation, PS #17623 4" deep, 6' South of the centerline of Davison Lake Road extending to the East &amp; West, which has a gravel surface, and 3' East of the centerline of Delano Road extending to the North &amp; South, which has a gravel surface. The North 1/4 corner of Section 1, T5N, R10E, Oxford Twp. (L-1) (as per the direction of the Oakland County Peer Group and was accepted as a common corner with L-13.</li> </ul>		
I found a second 1/2" Iron Rod 9.13 a feet to the Southeast.  Witnesses from Certificates of Survey's #1, 2, 3 & 4 were used to verify the location of the found 2" diameter brass cap stamped Oakland County Remonumentation, PS #17623		
I accepted the found 2" diameter brass cap st corner position for L-13.  FIELD MEASUREMENTS BETWEEN  L-13 to N-13 2654.19 Ft., GLO = 40 chains or L-13 to K-13 2646.07 Ft., GLO = 40 chains or C. Description of monument for corner and access	2640.00 Ft. 2640.00 Ft.	PA 345 OF 1990 PEER COUNTY
L-13 I found 2" diameter brass cap stamped Oakland County Remonumentation, PS #176232  S58 E 38.77' Fnd PK Nail w/Oakland County Remon. Washer, PS #17623 SW face Power Pole  N56 E 47.11' Fnd PK Nail w/Oakland County Remon. Washer, PS #17623 SW face 9" & 10" Twin Oak  S30'W 65.92' Fnd PK Nail w/Oakland County Remon. Washer, PS #17623 SE face 9" Cherry  S72'E 9.13 feet found 1/2" Iron Rod (has been previously accepted & used for L-1 Oxford Twp)  The selected location is accepted by me and is generally accepted by Professional Surveyors as the best variable evidence of the position of the original corner.  PROFESSIONAL  PROFESSIONAL  PROFESSIONAL		
The selected location is accepted by me and is growing position of the original corner.	enerally accepted by Professional Surveyo	ors as the best available evidence of the KENNEDY
Signed by	D	toher 4, 19
- L-T	7623 FORM APPROVED BY MI	
LIBER 3005 PAGE 0293		