

# SURVEY & REMONUMENTATION

MAR 13 1998

## REMONUMENTATION

### SECTION

### LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

97 NOV 12 PM 3:02

For corners in

Lapeer

(County)

Located In:  
Dryden Township

Corner Code #

1. Public Land Survey

T 6N R 11E

A-11

2. Property Controlling  
in Section

S

T

R

3. Miscellaneous  
Property in Sec.

S

T

R

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, Huston K. Kennedy, in a field survey on 8/15, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

#### A. Description of original monument and accessories and/or subsequent restoration:

1817-GLO Wampler, D.S., No post was set

1.) 1993-Kennedy, PS #17623; LCRC L.5, pg.50 - Fnd a Concrete Monument (M-11)

2.) 1977-Kennedy, PS #17623; Unrecorded Survey - Set a Concrete Monument

3.) 1989-Carlson, PS #9189; Unrecorded Survey - Fnd a Concrete Monument

4.) 1989-Heil, PS #18998; Unrecorded Survey - Fnd a Concrete Monument (M-11)

5.) 1994-Kennedy, PS #17623; Unrecorded Survey - Fnd a Concrete Monument, used same wit as 1993 LCRC

#### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1997 Kennedy Surveying, Inc. - Kennedy, PS #17623 - Fnd 4" diameter Concrete Monument with 1/2" Iron Rod w/2" diameter brass cap stamped Lapeer County Remonumentation M-11, 1.2 feet above the ground with a fence-rock row extending to the North, South, East & West. The corner is being used and accepted as a common corner with Sections 25 & 36, T6N, R10E, Metamora Township (M-11)

Witnesses from LCRC #1, Survey #2 & 3 were used to recover and verify the location of the found 4" diameter Concrete Monument with 1/2" Iron Rod w/2" diameter brass cap stamped Lapeer County Remonumentation M-11.

I accepted the found 4" diameter Concrete Monument with 1/2" Iron Rod w/2" diameter brass cap stamped Lapeer County Remonumentation M-11 as the best evidence of the original corner position.

Field Measurements between see back side of LCRC

#### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-11 I accept the found 4" diameter Concrete Monument with 1/2" Iron Rod w/2" diameter brass cap stamped Lapeer County Remonumentation A-11

Due North 30.48' Fnd PK Nail & Remon Washer West face 33" Oak

Due West 20.60' Fnd PK Nail & Remon Washer North face 8" Maple

S44°W 28.56' Fnd PK Nail & Remon Washer NW face 27" Basswood

S61°E 34.59' Fnd PK Nail & Remon Washer NE face 39" Oak

N15°E 15.83' Fnd PK Nail & Remon Washer West face 9" Ash

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by

Date

Surveyor's Michigan License No.

17623

9/30/97



FIELD MEASUREMENTS BETWEEN

A-11 to A-10

No GLO

Unrecorded Survey by Carlson, PS #9189 (4/89) = 2548.12 Ft.  
GROUND-MEA (8/97) = 2548.59 Ft.

A-11 to A-12

No GLO

Unrecorded Survey by Kennedy, PS #17623 (10/77) = 2634.02 Ft.

A-11 to M-11

No GLO

Common Corner

M-11 to M-12

GLO = 40 chains or 2640.00 Ft.

Unrecorded Survey by Heil, PS #18993 (7/89) = 2632.40 Ft.

Unrecorded Survey by Kennedy, PS #17623 (9/94) = 2634.45 Ft.

GROUP  
RECORDED

*Ray J.*  
9-29-97