

SURVEY &
REMONUMENTATION

APR 28 1995

COMMISSION

1994 REMONUMENTATION PROGRAM
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

94 DEC 22 PM 2:02

LIBER NO. 05 PAGE NO. 178

REGISTER OF DEEDS
LAPPEER COUNTY MICHIGAN

For corners in DEERFIELD TWP.
LAPEER (County) Located in: Corner Code #

1. Public Land Survey T 09N R 10E M-9
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

Register of Deeds Stamp & File Number

4. Lot No. Recorded Plat
5. Private Claims

I, JONATHAN M. FIELD, in a field survey on SEPTEMBER 23 19 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1822 GLO; WAMPLER, D.S.; SET POST; BEECH 14 N6W 32LKS., BEECH 17 S41W 19LKS.

1978 BECK-GRAVLIN; GRAVLIN, P.S.#23510; SURVEY L.4, PG.674; NO OBJECT STATED; N75°W 30.56' FE POST, EAST, 42.35' 22" TWIN CHERRY, N65°E 29.50' FE POST

1978 BECK-GRAVLIN; GRAVLIN, P.S.#23510; SURVEY L.4, PG.948; NO OBJECT STATED; NO WITS GIVEN

1979 BECK-GRAVLIN; GRAVLIN, P.S.#23510; SURVEY L.5, PG.127; NO OBJECT STATED; NO WITS GIVEN

1980 BECK-GRAVLIN; GRAVLIN, P.S.#23510; SURVEY L.5, PG.789; NO OBJECT STATED; SAME WITS AS 1978 SURVEY ABOVE

1987 GRAVLIN, P.S.#23510; SURVEY L.7, PG.734; FND 1/2" IRON; SAME WITS AS 1978 SURVEY ABOVE

1989 GRAVLIN, P.S.#23510; LCRC L.4, PG.226; FND 1/2" IRON; SAME WITS AS 1978 SURVEY ABOVE

1991 GRAVLIN, P.S.#23510; LCRC L.4, PG.370; FND 1/2" IRON; SAME WITS AS 1978 SURVEY ABOVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994 ROWE ENG.; FIELD, P.S.#37276; FND CORRODED 1/2" ROD 2' E. OF C/L GRAVEL ROAD N-S & ON LINE W/ FENCE TO E. GLO NOTES FOR T9N-R11E INDICATE THAT THIS CORNER IS COMMON TO BOTH TOWNSHIPS RECOVERED 2 PREVIOUS WITNESSES INDICATING THAT FND ROD IS IN SAME POSITION AS 1978 BECK-GRAVLIN SURVEY L.4, PG.674

2639.36' M-9 TO M-10 (MEAS. BY OTHERS)
2635.06' M-9 TO M-8 (MEAS. BY OTHERS)

ACCEPTED 1/2" ROD AS A CAREFUL AND FAITHFUL PERPETUATION OF THE ORIGINAL CORNER POSITION OF BOTH M-9 T9N-R10E AND A-9 T9N-R11E

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-9 REMOVED OLD ROD, SET 1/2" ROD W/ STANDARD BRASS CAP
EAST, 42.42' SET NAIL W/ REMON TAG IN N. FACE TWIN 24" CHERRY
N40°E, 33.70' SET NAIL W/ REMON TAG IN NW FACE FE POST
N68°W, 30.49' FND NAIL W/DISK IN NE FACE FE POST
N81°W, 72.44' SET NAIL W/ REMON TAG IN S. FACE P.POLE
S18°W, 114.81' SET NAIL W/ REMON TAG IN E. FACE P.POLE

PEER GROUP
APPROVED LAND CORNER

Signed by JONATHAN M. FIELD
LAPEER COUNTY
Surveyor's Michigan License No. 37276

Date 12-8-94

RAY DAVID P. CO. SURVEYOR
DATE 12-22-94

LIBER 0005 PAGE 0178

