1211 6 2000

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 PAGE 351

STATE OF MICHIGAN

For corners in			LENAWEE COUNTY
Lenawee	Located In:	Corner Code #	FILED
(County)		1	
1. Public Land Survey	T R T R T R		14 DEC 1999 4:33:49 PM VICTORIA J. DANIELS REGISTER OF DEEDS
Property Controlling S in Section S S Miscellaneous S Property in Sec S	T R 30 T-5-S R-3-E	5	Register of Deeds Stamp & File Number
4. Lot No, Reco	orded Plat		A B C D E F G H 1 J K L M 1 2 3 4 7 8 9 10 11 12
in lines 1 and 2 above were in current manual of survey instruc Management or by a decree of a above were in conformance with	uirements of P.A. 74, Michigan I conformance with regulations tions of the United States Dep Court of Law and/or that the co the rules of the Michigan Boa	survey on November 29, 19 99, P.A. of 1970, the corner points mentioned and rules therefore as required in the partment of the Interior, Bureau of Landorner points mentioned in lines 3, 4 and 5 and of Land Surveyors or by a Decree of a re-monumented, recovered, found as	4 7 8 9 10 11 12 5 6 18 17 6 15 14 13 7 8 19 20 21 22 23 24 9 10 •30 29 28 27 26 25
NOTE: Not more than 4 c on this certificate.		wn and range, may be recorded	12 31 32 33 34 35 36 13
G.L.O. This corner 1973 Kenneth Surveys done by 1975± Werner Socenterline of Peningson 1980 Werner Sound 1984 Kenneth Surveys Michael Bauer 1997 Werner So	er not established by origuydam set iron pipe in lin Walter Frazier in 1964. ommer set a iron 3.09 Setecost Hwy. and the cent mmer found 3/4" iron rocuydam used the corner (Intolo found iron pipe cap mmer found 3/4" iron rocumer found 3/4" iron r	outh of the above iron pipe at inter erline of Feller Road to the East I in monument box Didn't describe the type of monum oped WES 12030 33' West of pave	ed over monument box
August 7, 1999 monument box w	I dug and found 3/4" iron ith adjusting rings to surf	od applied in restoring or reestablishing or reestablishing in rod in monument box that had be face of new asphalt pavement unty Re-mon cap on the existing 3	en paved over. August 9, 1999 I raised th

Description of monument for corner and accessories established to perpetuate locating the position of the corner: C.

3/4" iron rod with Lenawee County Re-mon cap stamped P.S. 13040 in monument box .

Fd iron pipe capped WES 12030 West 33.02 Fd small boat spike & washer in wood post N 75° W 34.96 Fd small boat spike & washer in TP S 60° E 53.92 MAG nail & Lenawee County Re-mon tag in TP S 20° W 89.93 MAG nail & Lenawee County Re-mon tag in EP N 40° E 55.74

West 1/4 corner Sec. 30 (iron pipe in swamp) West 1894.88 Center Sec. 30 (3/4" iron pipe recorded in Liber 5, Page 277) East 3175.51



Ratified by Peer Group in accordance with P.A. 345 Signed by Sleve & Richard Da Glenn E. Richard	Co. Rep- Service Richard	Date <u>December 7, 1999</u>
Surveyor's Michigan License No. 13040		FORM APPROVED BY MICHIGAN STATE SOARD OF LAND