

FILED

JAN 25 2000

SECTION

Filed under Remonumentation Act 345 of 1990
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 1 PAGE 322

STATE OF MICHIGAN
LENAWEE COUNTY

FILED

14 JUL 1999 6:32:38 PM

VICTORIA J. DANIELS
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

For corners in

Lenawee
(County)

Located In:

Corner Code #

1. Public Land Survey	T - 5-S	R - 5-E	G-11
	T	R	
	T	R	
	T	R	
2. Property Controlling in Section	S	T	R
	S	T	R
3. Miscellaneous Property in Sec	S	T	R
	S	T	R

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Glenn E. Richard, in a field survey on July 6, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. 1819 Joseph Fletcher set post cor. Sec.'s 27, 28, 33 & 34 Elm 60 S 80 W 24 Lynn 12 S 33 E 10
1979 Kenneth Suydam RLS 17636 "Found large hex iron in pavement" and recorded it in L 4 P 263
1992 AES Found large hex iron
1997 I found large hex head bolt 6" deep. Replaced with 3/4" X 3' iron pipe and set monument box in newly layed asphalt pavement.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

July 6, 1999 Found 3/4" iron pipe in monument box. Drove the iron pipe down with 5/8" X 3' re-rod inside of it and capped with Lenawee County re-mon cap stamped P.S. 13040

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County re-mon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner

Cut "X" on CMP N 55° W 36.02
Cut "X" on CMP N 55° E 36.24
fd nail & disc in E.P. N 40° W 49.36
dbl hd nail & Lenawee County Re-mon tag in E.P. S 5° W 291.83



Atified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date June 22, 1999

igned by Glenn E. Richard Date July 8, 1999
Glenn E. Richard

urveyor's Michigan License No. 13040