

JAN 22 2001

SECTION

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Lenawee

(County)

Located In:

Corner Code #



LIBER 2

PAGE 9

1. Public Land Survey

T-7-S R-5-E

M-10

T R

T R

T R

2. Property Controlling

S T R

in Section


S T R

3. Miscellaneous

S T R

Property in Sec

S T R



Register of Deeds Stamp & File Number

4. Lot No.

Recorded Plat

5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Glenn E. Richard

in a field survey on October 16, 2000

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1819 Joseph Fletcher D.S. Set 1/4 Sec. post Sycamore 12 N 20 E 12 B. Oak 10 N 80 E 8

1883 James Blair found corner; Set stone with "X" on top

1919 J.L. Richard set iron pipe 7.0' east of 1/4 corner Sec. 25

1969 I found the above iron pipe and set iron pipe 7.0' west for the East 1/4 cor of Sec. 25

1973 I found iron pipe

1978 I found 1/2 iron pipe and recorded it in Liber 4, Page 204 "X" on corrugated aluminum pipe. N 25 W 30.12.

Dbl hd nail & disc in E. face E.P. N 60 W 31.48

1981 The road was surveyed by the Lenawee County Road Commission Engineer and I believe they rebuilt the road and set the mon. box.

1984 I found iron pipe

1995 I found iron pipe

2000 David Erickson found 3/8" iron pipe in monument box. N 50 W 31.42 fd. nail & shiner E. side utility pole. North 52.06 3/4" pipe in mon. box (W. 1/4 corner Sec. 30)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

October 16, 2000 Fd 1/2" X 27" iron pipe in mon. box. Replaced it with 5/8" X 3' re-rod with Lenawee County re-mon cap stamped P.S. 13040. Probed but didn't find anything else.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County Re-mon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

Fd. "X" cut on corrugated aluminum pipe N 25° W 30.08

Fd. dbl nail & disc in E. face of E.P. N 60° W 31.37

Fd. David Erickson capped iron West 33.04

1 1/2" galv. pipe post N 30° E 61.46

3/4" iron pipe in mon. box A-10 7-6 North 52.06

The corner is 8± west of pavement center line



Ratified by Peer Group in accordance with P.A. 345

Co. Rep

Glenn E. Richard

Date September 26, 2000

Signed by

Glenn E. Richard

Date

Nov. 7, 2000

Glenn E. Richard

Surveyor's Michigan License No. 13040