

SURVEY & REMONUMENTATION

OCT 19 1998

SECTION _____

Filed under Remonumentation Act 345 of 1990
LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 1 PAGE 256

STATE OF MICHIGAN
 LENAWEE COUNTY
 FILED

15 SEP 1998 8:59:33 AM

VICTORIA J. DANIELS
 REGISTER OF DEEDS

For corners in

Lenawee (County)	Located In:	Corner Code #
1. Public Land Survey	T - 8-S R - 4-E	M-8
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

Register of Deeds Stamp & File Number

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

I, Glenn E. Richard, in a field survey on April 13, 19 98, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2								
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1819 Joseph Wampler set 1/4 Sec. post Aspen 18 N 50 E 5 Sycamore 6 N 3 E 13
 Couldn't find anything on this corner in any of the old survey records
 1980 Dug with back hoe and found large stone. Set 1" X 3' galv. pipe on line between M-7 and M-9 T8S R4E which is on east side of the stone 0.6± east of the top of the stone. I recorded it in L 4 P 330.
 1980± Lenawee County Road Commission rebuilt the road and set a monument box

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

April 13, 1998 Found iron pipe and monument box tipped to west at west edge of the pavement.
 Dug out iron pipe and the monument box and reset the box and set 5/8" X 3' re-rod with Lenawee County re-mon cap stamped P.S. 13040 by using the previously recorded witnesses and line between M-7 and M-9 T8S R4E

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 3' re-rod with Lenawee County re-mon cap stamped P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

- Fd. "X" on steel culvert S 85° W 15.19
- Fd. "X" on steel culvert S 30° W 28.90
- Fd dbl hd nail & disc in E.P. S 20° E 94.18
- NW cor of house foundation S 20° E 252.61

A-8 T8S R5E South 121.79



Ratified by Peer Group in accordance with P.A. 345 Co. Rep. Glenn E. Richard Date July 21, 1998

Signed by Glenn E. Richard Date Sept 14, 1998
 Glenn E. Richard

Surveyor's Michigan License No. 13040