Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

APR U 1 1996

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 001 PAUE 74

FILED 12:09 P.M.									
	NOV	21	1995						
LENAWEE COUNTY JEANETTE D. KNOX REGISTER OF DEEDS									
f Deeds Stamp & File Number									
CDEFGHIJKLM									
	-5	-	3	2	4				
	8	9	10	11	12-				
\exists									

COMMISSION

on this certificate.

For corners in				0,		
_Lenawee	Located In:	Corner Code #	.	ILED po		
1. Public Land Survey	T <u>-8-\$</u> R <u>-5-E</u> TR TR TR	<u>J-7</u>	LENAW JEANET	2 1 1995 TEE COUNTY TIE D. KNOX ER OF DEEDS		
2. Property Controlling in Section	S T R S T R		Register of Deeds \$	Stamp & File Number		
 Miscellaneous Property in Sec. 	STR STR		ABCDE	FGHIJKLM		
	Recorded Plat		3 4 7 8	9 10 11 12		
do hereby certify that under in lines 1 and 2 above we current manual of survey in Management or by a decree	r requirements of P.A. 74, Michigan are in conformance with regulation structions of the United States D of a Court of Law and/or that the	is survey on <u>June 13</u> 19 n. P.A. of 1970, the corner points men and rules therefore as required epartment of the Interior, Bureau of corner points mentioned in lines 3, 4 pard of Land Surveyors or by a Dec	ntioned 7 I in the 8 I Land 9 A and 5	16 15 14 13 21 22 23 24 28 27 26 25		
Court of Law; establishe expressed below:	d, re-established, monumented	, re-monumented, recovered, for n and range, may be recorded	, , , , ,	33 34 35 36		

Description of original monument and accessories and/or subsequent restoration:

G.L.O. 1820 Joseph Wampler set 1/4 sec post Aspen 16 N 75° W 2 Elm 6 S 4 E 9 September 18 & 19, 1876, B. Kent "South 1/4 post not found but line divided". November 30 & December 1, 1883, James Blair set stake & stakes 2 rods N& S.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

June 13, 1994, I dug with a backhoe across the road 4' to 5' wide. Found small pieces of brick and tile at a point between the section corners East and West. Set 3/4" X 3' gas pipe and capped P.S. 13040 at the mid point line between the section corners East and West. June 1995, replaced the gas pipe with a 30" Harrison Monument stamped G.E.R. P.S. 13040

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

30" Harrison Monument stamped G.E.R., P.S. 13040 and is accepted as the best available evidence of the position of the original corner.

"X" cut on end of C.M.P. N 20° W 22.14 "X" cut on end of C.M.P. N 45° E 24.40 Dbl nd nail and disc in Elec Pole N 80° E 75.44

Dbl hd nail and disc in RR tie post \$ 5° W 12.51

Date 10-9-95

Ratified by Peer Group in accordance with P.A. 345

Signed by_

Glenn E. Richard

Surveyor's Michigan License No. 13040

GLENN F

BRHACK