

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Luce (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 36 T 45N R 10W	12
	S 36 T 45N R 10W	13
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 12 03/22/2012 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(12-Sec. 36) South 1/16 corner, Section 36. Not previously monumented.

(13-Sec. 36) Southeast 1/16 corner, Section 36. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(12-Sec. 36) Established the position for the corner midway and on a straight line between Quarter  
corner 1327.27' south and Center of Section 36 1327.27' north.

(13-Sec. 36) Established the position for the corner at the intersection of straight lines connecting  
opposite 1/16 corners. From the position thus established, I found a 1.5" I.pipe, projecting 3.5  
ft., set loosely, placed by persons unknown for an approximate corner S50W, 80 ft. distant.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(12) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
6" Sugar N64W 10.05' mrkd "S1/16 BT"  
12" Sugar N16E 14.25' do  
9" Sugar N72E 24.4' do  
10" Sugar S63W 18.9' do  
Placed sq'd Pine post adjacent.  
Bearings are magnetic.

(13) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
24" Hemlock N17E 46.4' mrkd "SE1/16 BT"  
8" Sugar S85E 20.95' do  
12" Sugar S22E 15.4' do  
12" Sugar S71W 7.25' do  
Set sq'd Hemlock post adjacent.  
Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 07/12/2012

For the Michigan Department of Natural Resources, Forest Resources Division

