

SURVEY & REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Luce County Remonumentation Corner

FEB 23 2001

For corners in

SECTION

Luce County

Located in:

Corner Code #

1. Public Land Survey

T45N R11W

E-12

T R
T R
T R
T R
T R

2. Property Controlling
in Section

S

T R

3. Miscellaneous
Property in Sec.

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

LUCE COUNTY

REGISTER OF DEEDS

Recorded

Liber 3 page 955

02-12-2001 09:44:35

Kathy S. Mahar

Kathy S. Mahar, Register

REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, William L. Karr, in a field survey on October 3, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
(E-12) 1/4 Corner common to Sections 32 and 33 Township 45 North, Range 11 West.

1849 William Ives set post for corner.

Cedar 10 N86W 8
Spruce 12 N62E 13

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
(E-12) 1/4 Corner common to Sections 32 and 33 Township 45 North, Range 11 West.
This corner is being re-established as part of the Luce County Remonumentation Program.

Found no evidence of the original corner or subsequent restoration. Re-established the corner by single proportionate measurement using the Section corner 1/2 mile to the North and 1/2 mile to the South. Distance to the North and South is 2609.18 feet.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
(E-12) 1/4 Corner common to Sections 32 and 33 Township 45 North, Range 11 West.

Corner is a 1/2" x 48" re-rod with a stamped aluminum Luce County Remonumentation Corner cap.

Witnesses:

Cedar 6"	N05E	12.83 feet
Red Maple 6"	S87E	8.02 feet
Red Maple 15"	S54W	28.12 feet
White Birch 7"	N47W	4.83 feet

Bearings are compass bearings, corrected for declination (6° W), all distances are to a nail and tag in the side of the witness object unless otherwise noted.

Signed by

William L. Karr

Date

12/01/00

Surveyor's Michigan License No. 27450

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995