

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

LUCE

(County)

1 Corner
Located In:

Corner Code //

1 Public Land Survey

T R

T R

T R

T R

2 Property Controlling
in Section

S 22 T 46N R 9W

8

3 Miscellaneous

S T R

Property in Sec

S T R

Register of Deeds Stamp & File Number

4 Lot No

Recorded Plat

5 Private Claims

I, **Gerald L. Wiggins**, in a field survey on **6-6**, 19 **90**, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A Description of original monument and accessories and/or subsequent restoration:

8 West 1/16 Corner of Section 22. Not previously set.

B Description of corner evidence found and/or method applied in restoring or reestablishing corner.

8 Corner set M.P.O.L. between West 1/4 Corner and Center Corner of Section 22.

C Description of monument for corner and accessories established to perpetuate locating the position of the corner.

8 DNR Monument.

8" Cedar, N42°W, 10.1' & Twin 8" Maple, N15°W, 11.7' & 8" Maple, S24°E, 12.1' & 8" Hemlock, S30°W, 7.7'.

Signed by

Gerald L. Wiggins

Date 9-13-90

Surveyor's Michigan License No.

23521



FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN. 20, 1971
REVISED MAY 14, 1976
REVISED JAN. 1983