

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Luce (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 31 T 47N R 09W	11
	S T R	(GCDB 120120)
	S 31 T 47N R 09W	15
	S T R	(GCDB 120100)
	S T R	
3. Miscellaneous Property in Sec.		
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 02/05/15 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(11-Sec. 31) Southwest 1/16 corner, Section 31.
Not previously monumented.

(15-Sec. 31) West 1/16 corner between Section 31 T47N-R09W and
Section 6 T46N-R09W. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(11-Sec. 31) Established the position for the corner at the intersection of straight lines
connecting opposite 1/16 corners, those to the north, east, and west, being unmonumented. The
center-west 1/16 corner is calculated 20 chains (R) (1325.68' M) west of the intersection of 1/4
lines and 17.811 chains (R) (1180.58' M) east of A12, proportionate to the US record.

(15-Sec. 31) Established the position for the corner 20.00 chains, proportionate to the US record,
west of 1/4 corner B13 and on the Township line between B13 1323.91' east and A13 1178.28' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(11) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
5" Cedar S17°W 26.02' mrkd "SW1/16 BT"
4" Maple N78°W 20.97' do
5" Cedar S84°E 18.27' do
7" B.Spruce N58°E 19.54' do
E= 8116482.571 N= 183313.444

(15) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
10" Cedar S08°E 23.16' mrkd "W1/16 BT"
6" Cedar S60°W 16.41' do
5" Cedar N30°W 5.52' do
6" B.Spruce N62°E 5.28' do
E= 8116491.548 N= 182911.043

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID RJ0491: N= 184295.144 m. E= 8114483.019 m.

Signed by Stephan J. Szyszkoski Date 11/04/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division