

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47.. NR 10 W. .

Luce

COUNTY

DESCRIPTION OF CORNER Section corner common to Sec.'s 26-27-34-35

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 8" Cedar N 32° E 35 links
"S 26 NBT"

7" Cedar S 44° E 35 links
"S 35 NBT"

12" W. Pine S 9° W 69 links
"S 34 NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

Replaced section corner from one cedar B.T. in excellent condition (green)
bearing N 59° W 10½ links. Found no evidence of use.

Corner lies in wet cedar swamp. Corner found by J. Kutchera, Asst. Forester
and L. Rubick, Aide, while on timber management survey.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 11/13/57
REGISTERED LAND SURVEYOR