

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Luce Co.

Two Corners.

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>47</u> N. R. <u>11</u> E. W.	I-3, I-4
2. PROPERTY CONTROLLING IN SECTION _____	T. _____ N. S. R. _____ E. W.	_____
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. S. R. _____ E. W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on 4-24 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- I-3 Sec. Cor. 2-3-10-11, originally placed by Geo. H. Cannon D.S. in 1853, while making a correctional survey of the twp. Bearings were: Beech 10" S28°E 29 lks. and Sugar 12" N25°W 43 lks.
- I-4 Sec. Cor. bet. Secs. 10-11, originally placed by Geo. H. Cannon D.S. in 1853. Bearings were: Beech 12" S26°W 19 lks. and Beech 12" N43°E 22 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- I-3 Corner re-established by single proportionate measure bet. Corners, 1/2 mile North and one mile South.
- I-4 Corner re-established by single proportionate measure bet. Corners, one mile North and 1/2 mile South.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Placed 1" pipe with 4" aluminum cap at both corners.

- I-3 No witnesses available.
Corner lies 30' North of Camp #1 road.
- I-4 See Bearings:
8" R. Maple S20°E 13.7'
14" W. Birch S84°W 39.6'
Corner lies 34' South of E. and W. road in NE corner of R. Pine plantation.

SIGNED BY Billy D. Buckler DATE 6/27/73

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ CHIEF OF SURVEY PARTY DATE _____

APPROVED AND SIGNED BY _____ MICHIGAN REGISTERED LAND SURVEYOR DATE _____ (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____