

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

| | | |
|------------------------------------|------------------|---------------|
| Luce | Located In: | Corner Code # |
| (County) | | |
| 1. Public Land Survey | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling in Section | S 32 T 48N R 10W | 12 |
| | S T R | (GCDB 240120) |
| 3. Miscellaneous Property in Sec. | S 32 T 48N R 10W | 13 |
| | S T R | (GCDB 260120) |
| | S T R | |
| 4. Lot No. , Recorded Plat | | |
| 5. Private Claims | | |

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|---|----|---|---|----|---|----|---|----|---|----|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | | 5 | | | 4 | | 3 | | 2 | | 1 |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | | 8 | | | 9 | | 10 | | 11 | | 12 |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | | 17 | | | 16 | | 15 | | 14 | | 13 |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | | 20 | | | 21 | | 22 | | 23 | | 24 |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | | 29 | | | 28 | | 27 | | 26 | | 25 |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | | 32 | | | 33 | | 34 | | 35 | | 36 |
| 13 | | | | | | | | | | | | | |

I, Stephan J. Szyszkoski, in a field survey on 03/26/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(12-Sec. 32) Center-South 1/16 corner, Section 32. Not previously monumented.

(13-Sec. 32) Southeast 1/16 corner, Section 32. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(12-Sec. 32) Established the position for the corner midway and on a straight line between Quarter corner 1319.94' south and the intersection of 1/4 lines of Section 32 1319.94' north.

(13-Sec. 32) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(12) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
6" Balsam North 5.52' mrkd "S1/16 BT"
7" Maple N48°E 12.57' do
10" Cedar S40°E 36.09' do
8" Hemlock S37°W 23.01' do
E= 8108669.326 N= 192806.308

(13) Set 1"IDx48" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
20" Maple S65°E 108.75' mrkd "SE1/16 BT"
4" Cedar N71°W 63.79' do
8" Cedar N45°W 81.82' do
6" Cedar N02°E 89.26' do
E= 8109073.268 N= 192815.187

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID RJ0491: N= 184295.153 m. E= 8114482.997 m.

Signed by Stephan J. Szyszkoski Date 04/28/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division