

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

Luce COUNTY


T 49N R 9W

DESCRIPTION OF CORNER: East 1/16 Cor. bet. Secs. 3-10

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 6/25/71

WITNESSES TO CORNER..... 10" J. Pine S07°E 21.8'



8" J. Pine N41°W 30.9'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies in center line of E-W fireline.

Corner placed midway and on line bet. Sec Cor. to east and 4 Cor. to west

SURVEYOR'S SEAL

*Billy D. Buckler*

SIGNED Billy D. Buckler DATE 12/17/71  
REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68