

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Luce <small>(County)</small>	Located In:	Corner Code #	
1. Public Land Survey	T 49N R 10W	J3	_____
	T 49N R 10W	K3	_____
	T _____ R _____		_____
	S _____ T _____ R _____		_____
2. Property Controlling in Section	S _____ T _____ R _____		_____
	S _____ T _____ R _____		_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____		_____
	S _____ T _____ R _____		_____

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

Nov 08 2004

I, Stephan J. Szyszkoski, in a field survey on _____, 20____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- (J3) Quarter corner common to Sections 2-11. 1957 - Remonumented by Billy D. Buckler, RLS: Replaced 1/4 corner as perpetuated by Marcus Schaff, Reg. Surveyor. 2" iron pipe in place. Found one jackpine BT bearing S68E 15 links (down) in good condition. Also found jackpine BT for old effaced corner South and West of 1/4 corner. Set 1" ID I.pipe with 4" brass cap. 9" W.Pine N26E 72 links, 9" W.Pine S89W 82 links.
- (K3) Corner common to Sections 1-2-11-12. 1957 - Remonumented by Billy D. Buckler, RLS, from original Jack Pine BT NW 45 links, in good condition. Set 1.5" x 50" iron pipe 6" below ground surface. Corner falls in the intersection of fire lanes. 9" Jack Pine N70E 74 links, 6" Jack Pine S16E 62 links, 6" Jack Pine S14W 89.5 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- (J3) Recovered both the 1957 capped pipe, badly bent, and the Schaff 2" iron pipe, in good condition, at record bearing and distance from the 1957 NBTs, both in good condition with overgrown blazes. Straightened the 1957 monument and grouted it into the Schaff 2" ID iron pipe. The original BTs noted in the 1957 record were not recovered.
- (K3) Recovered and accepted a 1.5" dia. iron pipe at record bearing and distance from two remaining 1957 Jack Pine NBTs NE and SE, both in good condition with open blazes. The Jack Pine NBT SW is now gone. Left the monument in place and made new witnesses as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | |
|--|--|
| (J3) Reset 1957 1" ID I.pipe with 4" brass MI Dept. of Conservation cap in found 2" iron pipe. Set meas. nails in:
16" W.Pine N28E 47.65' mrkd "1/4S" *
18" W.Pine N88W 54.55' do *
7" J.Pine S56W 19.2' mrkd "1/4S NBT"
6" J.Pine S45E 31.6' do
Bearings are magnetic. Distances are to nail with tag. * denotes 1957 NBT. | (K3) Found 1.5" ID I.pipe. Set measuring nails in:
12" J.Pine N73E 49.8' old blaze *
10" J.Pine S10E 41.6' do *
12" J.Pine N30W 20.45' mrkd "S2 NBT"
14" J.Pine S48W 21.4' "S11 NBT"
Bearings are magnetic. Distances are to nail with tag. * denotes 1957 NBT. |
|--|--|

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6	5	4	3	2	1						
3									●	●		
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												



Signed by Stephan J. Szyszkoski
 Surveyor's Michigan License No. 33986

Date 12/20/04

For the Michigan Department of Natural Resources, Office of Land and Facilities