

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD


Luce COUNTY
T 50N R 8W

DESCRIPTION OF CORNER Meander Corner bet. Secs. 30-31, on East side of Culhaine Lake

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 8-19-71

WITNESSES TO CORNER..... 11" Cedar (NBT) N2°W 8.4'



9" Cedar (MCNBT) S9°E 9.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Meander Corner re-established on line between Sec. Corner, 601.' East and the Meander Corner, on West side of lake 3,086.' West.
Found no positive evidence of the original meander corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 9-22-71
REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing ✓