

SURVEY &
REMONUMENTATION

OCT 11 1994

COMMISSION

MACKINAC COUNTY REMONUMENTATION CORNER
LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Mackinac

(County)

Located In:

Corner Code 44

1. Public Land Survey T 40N R 4W J-7
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

RECEIVED & FILED
DIANE FRANK KOVICH
MACKINAC COUNTY CLERK OF DEEDS

SEP 6 1994

AM PM
Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

Neil E. Hill

August 22 94

I, Neil E. Hill, in a field survey on August 22, 19 94,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Set 6" Cedar for corner

	A	B	C	D	E	F	G	H	I	J	K	L	M
2		5		5		4		3		2		1	
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Various surveys in area

1977 the corner shows up on recordation Liber B, page 67

1994 found 1" iron pipe

P.Pole N05W 09.40'
11" W. Birch S85E 26.25'
3" Balsam S05E 13.60'



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted corner as found; placed 5/8" re-rod inside 1" pipe with 4" aluminum cap.

P.Pole N20E 09.82' (MDOT tag)
10" Birch S80E 26.82' (MDOT tag)
6" Maple S45E 20.57'
4" Balsam S25W 06.33'

ACCEPTED BY THE MACKINAC COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 8-16-94

James H. Dranger

Signed by Neil E. Hill P.S. Date August 22, 1994

Surveyor's Michigan License No. 27447

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
FILE FEE
Misc.

09-06-94 1CL3183

D-0285